

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-10416
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/> P <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Langlie Mattix Penrose Sand Unit
8. Well No. 142
9. Pool name or Wildcat Langlie Mattix; 7 RVRS-Q-Grayburg

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other ☐ **Water Injection Well**

2. Name of Operator
Pecos Production Company

3. Address of Operator
400 W. Illinois, Ste 1070, Midland, TX 79701

4. Well Location

Unit Letter J 1980 feet from the South line and 1980 feet from the East line

Section 22 Township 22S Range 37E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3337' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Repairs as follows:

5/14/03- MIRU PU & tag fill at 3397'.

5/15/03- ND WH & NU BOP. POOH w/tbg. Tag fill at 3429'. Circ & drill on fill. Cleaned out fill at 3457'.

5/16/03- Drill & clean out fill at 3463' & 3478'. Circ clean & pull bit up hole to 3209'.

5/19/03- RIH w/same bit. Tag at 3669'.

5/20/03- RIH & LDDC's. RIH w/AD-1 pkr hydrotesting IPC tbg to 5000 psi - no bad jts. Set pkr, LD & test annulus to 500 psi- ok.

ND BOP & NU WH.

5/21/03- RD PU.

5/29/03- Conduct MIT test - good test. Test witnessed by NM OCD - Buddy Hill.

5/30/03- Return well to injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dora Bustamante TITLE Engineer Asst. DATE 6/03/03

Type or print name Dora Bustamante Telephone No. (915) 620-8480

(This space for State use)

OC FIELD REPRESENTATIVE II/STAFF MANAGER JUN 17 2003

APPROVED BY Larry W. Wink TITLE _____ DATE _____

Conditions of approval, if any: