

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

| | |
|--|---|
| WELL API NO. | 30-025-34849 |
| 5. Indicate Type of Lease | STATE <input type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil / Gas Lease No. | |
| 7. Lease Name or Unit Agreement Name | EUNICE MONUMENT SOUTH UNIT |
| 8. Well No. | 709 |
| 9. Pool Name or Wildcat | EUNICE MONUMENT GRAYBURG |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | 3574' GL |

| | |
|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMITS" (FORM C-101) FOR SUCH PROPOSALS. | |
| 1. Type of Well: | OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> |
| 2. Name of Operator | CHEVRON USA INC |
| 3. Address of Operator | 15 SMITH ROAD, MIDLAND, TX 79705 |
| 4. Well Location | Unit Letter <u>K</u> : <u>1330'</u> Feet From The <u>SOUTH</u> Line and <u>2421'</u> Feet From The <u>WEST</u> Line Section <u>10</u> Township <u>21-S</u> Range <u>36-E</u> NMPM <u>LEA</u> COUNTY |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | 3574' GL |

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ C/O, ADD PERFS & ACIDIZE

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.


6-02-03: MIRU. REL TAC. TAG PBTD @ 3900. PUH TO 3720'.

6-03-03: PERF 3792-3814 & 3820-34'. TIH W/PKR & SET @ 3700. SPOT 1000 GALS 15% HCL. SET TOOLS. TREAT PERFS 3864-3876. SPOT 1000 GALS 15% HCL. SET TOOLS. TRT PERFS 3846-3858. SPOT ACID TO END OT TBG. SET PKR. TRT PERFS 3820-3834 W/2000 GALS 15% HCL. SPOT ACID TO END OG TBG. SET PKR. TRT PERFS 3792-3814' W/2000 GALS 15% HCL. PUH. SET BTM PKR @ 3735.

6-04-03: REL PKR. TIH W/GAS SEPR, SN, & 2 7/8" TBG.

6-05-03: PU PMP & RDS. HANG WELL ON. RIG DOWN. TURN WELL OVER TO PRODUCTION.

FINAL REPORT



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Leake TITLE Regulatory Specialist

DATE 6/9/2003

TYPE OR PRINT NAME Denise Leake

Telephone No. 915-687-7375

(This space for State Use)

APPROVED Cheryl W. Wink TITLE OC FIELD REPRESENTATIVE II / STAFF MANAGER

JUN 17 2003

DeSoto/Nichols 12-93 ver 1.0