State of New Mexico

Submit 3 Copies Form C-103 Energy, Minerals and Natural Resources Department to Appropriate District Office Revised 1-1-89 DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION WELL API NO. P.O. Box 2088 30-025-DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease STATE 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: OIL WELL GAS WELL OTHER Name of Operator 8. Well No. 9. Pool name or Wildrat ess of Operator Feet From The Line Unit Letter **NMPM** Section Township Range County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. POUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed e to get the wall plugges can not feid a rig. Lam on the list up BC malosocates, Sunset g as hond as I can. THE OIL CONSERVATION DIVISION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TELEPHONE NO. TYPE OR PRINT NAME OC FIELD REPRESENTATIVE INSTAFF MANAGES (This space for State Use)

CONDITIONS OF APPROVAL



July 20, 2005

Spence Energy Company Attn: Clay Spence Kellahin State 14-2 Lea County, NM

Dear Mr. Spence:

- (1) MIRU
- (3) RU W/L & set 5-1/2" CIBP @ 4100", dump bail cmt., tag.
- (4) RIH w/ tbg. 4000', circulate w/ MLF.
- (5) Pull to 1732', spot 25 sx. cmt., may have to tag.
- (6) Pull to 400', spot 25 sx. cmt., WOC & tag.
- (8) RDMO. Cut off wellhead & anchors, install dry hole marker, and clean (7) 60' - surface, tag. location.

Quote: \$18,712.00

Quote will expire 90 days from July 20, 2005.

BASiC Energy Services will furnish the workstring.

Spence will furnish fluid disposal if needed.

This quote is based on information furnished to Basic Energy by your company. In the event operations are delayed or restricted because of unknown wellbore conditions or changes beyond our control to original approved regulatory form, charges will revert to standard hourly rates until such problems are corrected. In the event that this occurs, your company representative will be notified. As of March 01, 2003, all anchors must have been tested within the last two years.

Thank you for this opportunity to furnish this quote for your plugging and abandonment.

Sincerely

Area Manager