New Mexico Oil Conservation Division, District I

1625 N. French Drive

Form 3160-5 (August 1999) Hobbs, NM 88240

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

Lease Serial No.

If Indian, Allottee or Tribe Name

Well

NM 109434

abandoned wen. Ose Form 3100-3		
SUBMIT IN TRIPLICATE - Other in	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Gas Well X Other	8. Well Name and No. Burrus 23 Federal #1	
Name of Operator Chesapeake Operating, Inc.	9. API Well No.	
3a. Address P. O. Box 11050 Midland TX 79702-8050	3b. Phone No. (include area code) (432)687-2992	30-025-36566 10. Field and Pool, or Exploratory Area
	Trinity; Wolfcamp	
 Location of Well (Footage, Sec., T., R., M., or Survey Des. 990' FSL & 2170' FEL, Section 23, T12S, R38E 	11. County or Parish, State Lea New Mexico	
12. CHECK APPROPRIATE BOX(E	S) TO INDICATE NATURE OF NOTICE	E, REPORT, OR OTHER DATA

TYPE OF SUBMISSION TYPE OF ACTION Acidize Production (Start/ Resume) Water Shut-Off Deepen Notice of Intent Alter Casing ☐ Fracture Treat Reclamation Well Integrity Other Convert to a Subsequent Report Casing Repair New Construction Recomplete Water Supply Change Plans Plug and Abandon Temporarily Abandon

Water Disposal

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plug Back

OBJECTIVE: To convert well to a water supply well for future water flood unit. After the Tubb is perforated, we need to test the water quality before we can finalize our waterflood plans.

PROCEDURE:

☐ Final Abandonment Notice

1. MIRU workover rig. RU BOP. MI and rack 2 3/8" J-55 tbg.

2. RU wireline co. Perforate Tubb 7317-64 (47') w/4 JSPF, 4" HSC casing gun, 90 degree phasing.

3. RIH w/2 3/8" J-55 tbg and pkr to 7364'. Spot acid across perfs. Pull packer up to 7200' and acidize Túbb w/3000 gal 15 neFe acid dropping 200 7/8" ball sealers evenly througout job. displace acid to perfs and SI 30 mins.

4. Swab well back to determine rate. catch several water samples for analysis after load is recovered.

5. POH w/pkr, lay down tbg. RD BOP. Secure well head. rig down.

Convert to Injection

14. I hereby certify that the foregoing is true and correct							
Name (Printed/Typed)	Title						
Brenda Coffman	Regulatory Analyst						
Signature	Date						
Drenda Coffman	04/06/2005						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							

			,TEC			 	THIS	SPACE FOR FEDERAL OR
Approved b	y/\U		SGD.	DA	VID VID		GL	
Conditions	 				:			of this notice does not warrant or those rights in the subject lease
which wou								

Title 18 U.\$.C. Section 1001, makes it a crime fol any person knowingly and willfully to m fraudulent statements of representations as to any matter within its jurisdiction.

Accepted For Record Only! Approval Subject To Like Approval By The New Mexico Oil Conservation Division! TA Approval Will Be Required While Well Is Not Being Utilized. Without Production, Lease NM-109434 Will Expire 11/30/2012, The End Of Its Primary Term!

(Instructions on reverse) GWW