

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-07302
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name H. V. Black
8. Well Number #1
9. OGRID Number 227103
10. Pool name or Wildcat South Knowles (Devonian)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Platinum Exploration Inc

3. Address of Operator
550 W. Texas, Suite 500 Midland, TX 79701 432-687-1664

4. Well Location
Unit Letter K : 1980 feet from the South line and 1980 feet from the West line
Section 13 Township 17S Range 38E NMPM- Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3685' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Re-entry & Deepen ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

06/15/05-07/20/05 RU PU & reverse unit. NU BOP. RIH & tag cmt @ 80'. Drill hard cmt from 80'-250', circ cln. Drill out hard cmt from 250'-283', circ clean. Drill out hard cmt from 283'-330', fall out & circ clean. PU swivel & wash to TOC @ 2500', circ clean & test cst to 1000 psi. Drill out contaminated cmt & mud to 2839'. Fell out & cont. to wash heavy mud to 5865'. Tag cmt @ 5865'. Drill out hard cmt from 5865'-6135', circ clean. RIH to 8200' & circ out heavy mud. Tag @ 8630', circ clean. Drill out med hard cmt from 8630' - 9060', fall out & circ clean. RIH to 9299'. Drill soft cmt from 9299'-9620', fall out & circ cin. RIH & tag @ 12038', circ hole. RU Schlumberger & run USIT log from 12038-4500'. POOH & RD Schlumberger. Set pkr @ 11792' - test csg to 1400 psi. Unset pkr @ 8702'. Set RBP @ 11950', test to 1500 psi - OK. Isolate csg leak between 8513-9832'. RIH & latch onto RBP @ 11950' & unset plug. Set plug @ 9644' & test to 1500 psi - OK. Set pkr @ 8702'. Test between pkr & plug to 1500 psi. Isolate csg leaks between 8513'-8702' & 9644'-9832'. Unset pkr & RBP. Set RBP @ 10913'. RIH w/ cmt retainer. RU Schlumberger & test lines. Pump 260 sx CI H cmt. Sting out of retainer & pull 9 jts tbg. Set @ 8729'. RIH & set pkr @ 7885'. Pump 170 sx CI H cmt. Unset & POOH w/ pkr. RIH & tag @ 7890'. Drill out hard cmt from 7890'-8414' & circ clean. Test csg to 1500 psi - OK. Drill hard cmt from 8414'-8650', circ clean & test csg to 1500 psi - OK. Tag @ 9012', mill on cmt retainer. Circ clean. Drill retainer. loose & push to TOC @ 9180'. Drill hard cmt to 9200'-9357', circ clean. Drill hard cmt from 9357'-9725', soft cmt from 9725'-9780', fall out @ 9780' & circ clean. (cont.)

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Gloria Holcomb TITLE Agent DATE 07/29/05

Type or print name Gloria Holcomb E-mail address: gholcomb@t3wireless.com Telephone No. 432-687-1664
For State Use Only

APPROVED BY: [Signature] TITLE PETROLEUM ENGINEER SEP 15 2005
Conditions of Approval (if any):

H. V. Black #1
C-103 continuation

Test csg to 1500 psi – Good. Latch & unset RBP. Mill out CIBP @ 12038' & push to 12138'. Mill over junk & wash down to TD @ 12166'. Mill to 12168'. Drill new formation from 12168'-12218', circ cln. RIH w/ 5 ½ HD Pkr and set @ 12012'. RU Schlumberger and pump 2500 gals 15% HCL. RD Schlumberger. RIH w/ pump & tbg. Tbg set @ 11274'. RD PU. Clean location.