## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-025	5-37128
DISTRICT II			5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410			6. State Oil & Gas Lease No.	
	TICES AND REPORTS ON WE	LLS	7. Lease Name or Unit Agreen	nent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			NORTH HOBBS (G/SA) UNIT	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			Section 29	
Type of Well:     Oil Well X	Gas Well Other		8. Well No. 636	
2. Name of Operator			9. OGRID No. 157984	
Occidental Permian Ltd.  3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS,	NM 88240 505/39	7-8200		MODDS (G/S/1)
4. Well Location				
Unit Letter F: 1760	Feet From The NORTH	Feet	From The WEST	_ Line
Section 29	Township 18-S  11. Elevation (Show whether DF, Ri	Range 38-E	, NMPM	LEA County
	3644' GR	Ab, K1 GK, etc.)		
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	NS. DLUG & A	ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	ТЈОВ	
OTHER:		OTHER:	New Well Completion	n X
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
proposed work) 622 11622 11661101 manple completions in the control and the proposed completions of the completions.				
1. RUPU. Drill out DV tool @3476'. Tag PBTD @4298'.				
<ol> <li>Perforate the following intervals; 4158-71, 4178-81, 4229-36, 4243-48, and 4255-66 using 2 spf, 120 deg sp ph. (44 holes).</li> <li>Perforate the following intervals; 4209-22 using 1 spf, (14 holes).</li> </ol>				
4. Stimulate perfs 4158 to 4266 w/3600 g 15% NEFE HCL acid in 31 settings.				
5. RIH Reda ESP on 126 jts 2-7/8" tbg w/drain valve. Intake set @4095'.				
6. Install QCI wellhead connection	. NU wellhead.			
7. RDPU. Clean Location.			<b>⇒</b>	13 x 6
Rig Up Date: 09/02/2005			4	100 B
Rig Down Date: 09/08/2005			, 3)	
	Arris and complete to the best of my limer	dodgo and haliaf. I fouther contic.	that any mit on hallowers and son 191	o control of the cont
I hereby certify that the information above is constructed or	true and complete to the best of my know	— reage and benef. I further certify	that any pit or below-grade tank i	nas deen/will de
closed according to NMOCD guidelines	, a general permit	or an (attached) alternative plan	e OCD-approved	1808.85
SIGNATURE Robert	Fillet	TITLE Workover Com	pletion Specialist DAT	E 09/09/2005
TYPE OR PRINT NAME Robert Gill	ert E-mail address:	robert_gilbert@oxy.com	TELEPHONE NO.	505/397-8206
For State Use Only				
APPROVED BY SEP 1 9 2005  CONDITIONS OF APPROVAL FANY:				