Submit 3 copies

State of New Mexico

Form C-103

to Appropriate District Office	Energy, Minerals and Natural	Resources Department	Revised 1-1-89
DISTRICT I	OIL CONSERVAT	TON DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2		30-025-06686
DISTRICT II	Santa Fe, New Mex		5. Indicate Type of Lease
P.O. Box Drawer DD, Artesia, NM 88210			STATE ☐ FEE 🗹
DISTRICT III			6. State Oil / Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOT	TICES AND REPORTS ON W	ELLS	
	POSALS TO DRILL OR TO DEE RVOIR. USE "APPLICATION FO C-101) FOR SUCH PROPOSALS	R PERMI	Lease Name or Unit Agreement Name C.L. HARDY
1. Type of Well: OIL WELL WELL OTHER		03456785707	
2. Name of Operator CHEVRON US	ISA INC		8. Well No. / 3
3. Address of Operator 15 SMITH RD	D, MIDLAND, TX 79705		9. Pool Name or Wildcan
4. Well Location Unit Letter K: 1980' Feet From The SOUTH Line and 1980' Feet From The WEST Line			
Section 20 Township 21-S Range 37-E NMPM LEA COUNTY			
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3305' GL			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTIO	ON TO:	SI	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
	CHANGE PLANS	COMMENCE DRILLING OP	PERATION PLUG AND ABANDONMENT
TEMPORARILY ABANDON		CASING TEST AND CEME	_
PULL OR ALTER CASING OTHER:		OTHER:	ADD PERFS & STIMULATE
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any			
proposed work) SEE RULE 1103.			
8-17-05: MIRU. TIH W/DRILL BIT ON BIT SUB. 8-18-05: TAG @ 3908. C/O WELLBORE. DRILL TO CMT RET @ 3939. START DRILLING RET. DRILL ON CIBP 2'. 8-19-05: TAG CIBP. START DRILLING ON CIBP. 3 INCHES. 8-22-05: TIH W/CONE BUSTER MILL. TAG CIBP. DRILL ON CIBP & CMT. FELL OUT OF CMT @ 3978'. 8-23-05: TAG @ 5079. 36' FILL. PERF 3687-91, 3700-06, 3712-18, 3722-28, 3732-40, 3744-52, 3767-73, 3780-88, 3812-20, 3878-82, 3906-12, 3918-22, 3932-36, 3949-53, 3963-67. TIH W/PKRS ON WS. SPACE OUT PKRS. 8-24-05: ACIDIZE PERFS 3687-3967' W/5600 GALS ACID. RU SWAB. REL PKR. 8-25-05: SWABBING. WELL STARTED FLOWING. 8-26-05: FLOW WELL TO TANKS. 8-29-05: TIH W/116 JTS 2 7/8", TAC, 11 JTS 2 7/8", 1 JT 2 7/8" IPC, SN, TBG SUB, DESANDER, MJ. SET TAC. TIH W/PMP & RODS. RIG DOWN. FINAL REPORT			
Thereby certify that the information above to true and complete SIGNATURE		egulatory Specialist	DATE <u>8/31/2005</u>
	enise Pinkerton		Telephone No. 432-687-7375

APPROVED CONDITIONS OF APPROVAL TO ANY:

PETROLEUM ENGINEER

DATE