

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

APACHE CORPORATION

3a. Address

6120 S. YALE, STE. 1500, TULSA, OK 74136

3b. Phone No. (include area code)

918-491-4980

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

AT SURFACE- 330' FSL & 1650' FEL, UNIT O

AT PROPOSED PROD. ZONE- 330' FSL & 1650' FEL, UNIT O

5. Lease Serial No.

NMLC-031741-A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

HAWK A-5 # 3

9. API Well No.

30-025-37380

10. Field and Pool, or Exploratory Area

WANTZ ABO

11. County or Parish, State

LEA CO., NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other SPUD, SURF. CSG.
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	TD, LOG, PROD. CSG.
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

8/7/05 SPUD 12 1/4" HOLE. DRILL & SURVEY TO 1230'. CIRCULATE FOR CSG. DROP TOTCO-POH W/ BIT RIG UP CSG. CREW - SAFETY MEETING.

8/8/05- DRILL & SURVEY TO 7500'. RIH 28 JTS 1233.99' 8 5/8" 24# J55 ST&C CSG W/ 9 CENTRALIZERS. CIRCULATE. BJ CMT SHOE @ 1230- FC @ 1183 W/ 375 SX 35.65 POZ
8/22/05 W/ 6% GEL + 2% CACL + 1/4" CF = 126 BBLS 12.7# SLURRY W/ 1.88 YIELD & 200 SX. CLASS C + 2% CACL + 1/8" CF = 48 BBLS 14.8# SLURRY W/ 1.35 YIELD- PLUG
BUMPED & HELD - CIRC 135 SX CMT TO PIT WOC. CUT OFF CSG- WELD ON HEAD. NU BOP EQUIP. RIH W/ BIT & BHA. SLIP & CUT 120' DRILLING LINE. RIH W/ DP.
DRILL CMT & FLOAT EQUIP. DRILL NEW FORMATION 1230-1490. DRILL 3359-3583- MUD LOGGER ON @ 3500'. DRILL 6291-6511 - MADE CONNECTION- LOST
WEIGHT & PUMP PRESSURE. START POH. REPAIR BOOM. POH - LEFT 23 DC'S IN HOLE- BOX CRACKED. START RIH W/ 7 5/8". OS W/ 6" SPIRAL GRAPPLE. CONT
RIH W/ OS- CATCH FISH @ 5823. START POH W/ FISH. REPLACE HYDRAULIC HOSE ON ROUGHNECK. CONT POH W/ FISH. REPLACE HYDRAULIC HOSE ON
BOOM. LAY DOWN FISH. INSPECT DRILL COLLARS. WAIT ON DRILL COLLARS- BIT SUB & JUNK BASKET. RIH W/ BIT # 4. DRILL 7365-7500. CIRCULATE FOR LOGS.
SURVEY @ 7456= 2.75. START POH W/ BIT- WORK THRU TITE SPOT 2044 W/ KEY SEAT WIPER. REPAIR DRUM CHAIN. CONT POH - WORK THRU TITE SPOT 2680
W/ BIT. FINISH POH W/ BIT. HALLIBURTON RAN DUAL LATEROLOG MICROGUARD 7491-3400; COMPENSATED SONIC LOG 7440-200; DUAL SPACED NEUTRON
SPECTRAL DENSITY 7415-3400. RIH 148 JTS 6504.39' 5 1/2" 17# J55 LT&C CSG & 1 JT 14.14' 5 1/2" 17# J55 LT&C MARKER JT W/ 36 CENTRALIZERS & 22 JTS 990.32'
5 1/2" 17# L80 LT&C CSG. WAIT ON BULK CMT. BJ CMT SHOE @ 7500 - FC @ 7454 W/ 1100 SX 50:50 POZ C W/ 10% GEL = 5% SALT + 1/8" CF = 478 BBLS 11:8#
SLURRY W/ 2.44 YIELD & 1200 SX 50:50 POZ C W/ 2% GEL + 5% SALT = 276 BBLS 14.2# SLURRY W/ 1.29 YIELD- DISPLACE W/ 102 BBLS KCL WATER- LOST WATER
SUPPLY - SHUT DOWN 4 MINUTES- RESUME DISPLACEMENT- PRESS. 2730- SHUT DOWN - 71 BBLS CMT IN CSG= 309 SX CMT- CIRC 22 BBLS CMT TO PIT= 50 SX
TO PIT ND BOP - SET SLIPS- CUT OFF CSG- RELEASE RIG @ 11:30 PM 8/22/2005

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Lana Williams

Title SR. DEPT. ASSISTANT

Signature

Lana Williams

Date

9/7/05

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Office

Date

ACCEPTED FOR RECORD

SEP - 8 2005

GARY GOURLEY
PETROLEUM ENGINEER

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)