Submit 3 Copies To Appropriate District State of New N	Aexico	Form C-103
Office Energy, Minerals and Na	utural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API	NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATIO)25-37398
District III 1220 South St. Fr 1000 Rio Brazos Rd., Aztec, NM 87410	rancis Dr. 5. Indicate	Type of Lease TE X FEE
District IV Santa Fe, NM		l & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WEL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101	PLUG BACK TO A	ame or Unit Agreement Name
PROPOSALS.) 1. Type of Well: Oil Well 🔀 Gas Well 🗌 Other	8. Well Nu	mhan
2. Name of Operator	9. OGRID	
Texland Petroleum-Hobbs, LLC	1133	
3. Address of Operator		ame or Wildcat
777 Main Street, Suite 3200, Fort Worth, Te	xas 76102 Lovi	ngton Drinkard
4. Well Location Unit Letter J: 1740 feet from the Sout	h	Fach
		eet from the <u>East</u> line
Section 2 Township 17S 11. Elevation (Show whether 1	Range 36E NMPM	Lea County
	3837' GL	
Pit or Below-grade Tank Application or Closure		
Pit typeDepth to GroundwaterDistance from nearest free	h water well Distance from near	est surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume	bbls; Construction Mat	
12. Check Appropriate Box to Indicate	Nature of Notice, Report or (Other Data
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🔲	REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS CASING/CEMENT JOB	ALTERING CASING AND A A
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL	COMMENCE DRILLING OPNS CASING/CEMENT JOB	
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: Image: Completed operations, (Clearly state and completed opera	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER:	
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: Image: Completed operations. 13. Describe proposed or completed operations. (Clearly state a of starting any proposed work).	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER:	
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: Image: Completed operations, (Clearly state and completed opera	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER:	
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: Image: Complete and the second sec	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER: Il pertinent details, and give pertine tiple Completions: Attach wellbore	P AND A
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: Image: Completed operations. 13. Describe proposed or completed operations. (Clearly state a of starting any proposed work).	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER: Il pertinent details, and give pertine tiple Completions: Attach wellbore	P AND A
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: Image: Complete and the second sec	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER: Il pertinent details, and give pertine tiple Completions: Attach wellbore	P AND A
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: Image: Complete and the proposed of complete and the proposed work). SEE RULE 1103. For Multiple completion. Texland is requesting permission to the proposed TD. TD: changed to 8350'	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER: Il pertinent details, and give pertine tiple Completions: Attach wellbore	P AND A
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: Image: Complete and the proposed of complete and the proposed work. 13. Describe proposed or complete operations. (Clearly state a of starting any proposed work). SEE RULE 1103. For Multor recompletion. Texland is requesting permission to the proposed TD.	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER: Il pertinent details, and give pertine tiple Completions: Attach wellbore	P AND A
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: Image: Complete and the proposed or completed operations. (Clearly state a of starting any proposed work). SEE RULE 1103. For Multiple or recompletion. Texland is requesting permission to the proposed TD. TD: changed to 8350' Surface csg and cmt changed to: w	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER: Il pertinent details, and give pertine tiple Completions: Attach wellbore to change the csg/cmt prod change the csg/cmt prod change the csg/cmt prod csg; Cmt w/850 sks, cin	P AND A
TEMPORARILY ABANDON CHANGE PLANS Image: Change Pull OR ALTER CASING Image: Change Pull OR ALTER CASING PULL OR ALTER CA	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER: Il pertinent details, and give pertine tiple Completions: Attach wellbore to change the csg/cmt prod change the csg/cmt prod change the csg/cmt prod csg; Cmt w/850 sks, cin	P AND A
TEMPORARILY ABANDON CHANGE PLANS Image: Change Pull or alter casing PULL OR ALTER CASING MULTIPLE COMPL Image: Change Pull or alter casing OTHER: Image: Change Pull or completed operations. Image: Change Pull operations. 13. Describe proposed or completed operations. Image: Clearly state a of starting any proposed work). SEE RULE 1103. For Mull or recompletion. Texland is requesting permission to the proposed TD. Image: Clearly state at the proposed TD. TD: Changed to 8350' Surface csg and cmt changed to: Image: State at the production csg changed to: Production csg changed to: Image: State at the production csg changed to:	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER: Il pertinent details, and give pertine tiple Completions: Attach wellbore to change the csg/cmt prod change the csg/cmt prod change the csg/cmt prod csg; Cmt w/850 sks, cin	P AND A
TEMPORARILY ABANDON CHANGE PLANS Image: Change Pull or alter casing PULL OR ALTER CASING MULTIPLE COMPL Image: Change Pull or alter casing OTHER: Image: Change Pull or completed operations. Image: Change Pull operations. 13. Describe proposed or completed operations. Image: Clearly state a of starting any proposed work). SEE RULE 1103. For Mull or recompletion. Texland is requesting permission to the proposed TD. Image: Clearly state at the proposed TD. TD: Changed to 8350' Surface csg and cmt changed to: Image: State at the production csg changed to: Production csg changed to: Image: State at the production csg changed to:	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER: Il pertinent details, and give pertine tiple Completions: Attach wellbore to change the csg/cmt prod change the csg/cmt prod change the csg/cmt prod csg; Cmt w/850 sks, cin	P AND A
TEMPORARILY ABANDON CHANGE PLANS Image: Change Pull or alter casing PULL OR ALTER CASING MULTIPLE COMPL Image: Change Pull or alter casing OTHER: Image: Change Pull or completed operations. Image: Change Pull operations. 13. Describe proposed or completed operations. Image: Clearly state a of starting any proposed work). SEE RULE 1103. For Mull or recompletion. Texland is requesting permission to the proposed TD. Image: Clearly state at the proposed TD. TD: Changed to 8350' Surface csg and cmt changed to: Image: State at the production csg changed to: Production csg changed to: Image: State at the production csg changed to:	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER: Il pertinent details, and give pertine tiple Completions: Attach wellbore to change the csg/cmt prod change the csg/cmt prod change the csg/cmt prod csg; Cmt w/850 sks, cin	P AND A
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: Image: Complete c	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER: Il pertinent details, and give pertine tiple Completions: Attach wellbore to change the csg/cmt prod change the csg/cmt prod cla 12 1/4" hole to csg; Cmt w/850 sks, cin cla 7 7/8" hole to 8350 will be tied into surface	P AND A
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL I3. Describe proposed or completed operations. (Clearly state a of starting any proposed work). SEE RULE 1103. For Multor recompletion. Texland is requesting permission to the proposed TD. TD: changed to 8350' Surface csg and cmt changed to: with 8 5/8" 24# and/or 9 5/8" 36# Production csg changed to: will di 17# csg; Cmt w/1105 sks; TOC I hereby certify that the information above is true and complete to the grade tank has been/will be constructed or closed according to NMOCD guideline	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER: Il pertinent details, and give pertine tiple Completions: Attach wellbore to change the csg/cmt prod change the csg/cmt prod cla 12 1/4" hole to csg; Cmt w/850 sks, cin cla 7 7/8" hole to 8350 will be tied into surface	P AND A
TEMPORARILY ABANDON CHANGE PLANS Image: Change Pull OR ALTER CASING Image: Change Pull Or ALTER CASING Pull Or ALTER CASING Pull Or ALTER CASING Image: Change Pull Or ALTER CASING Pull Or ALTER CASING Pull Or ALTER CASING Pull OF A STATURE Image: Change Pull Or ALTER CASING Pull Or ALTER CASING Pull OF A STATURE Pull OF A STATUR Pull OF A STATUR Pull OF A STATUR PULL OF A STATUR PUll OF A ST	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER: Il pertinent details, and give pertine tiple Completions: Attach wellbore to change the csg/cmt proc change the csg/cmt proc clar 12 1/4" hole to csg; Cmt w/850 sks, cin clar 7 7/8" hole to 8350 will be tied into surface best of my knowledge and belief. I - , a general permit or an (attached) Production Analyst	PANDA The proposed completion The dates, including estimated date and and and by od c 2230', Run c to surface r, Run 5 1/2" c csg. atternative OCD-approved plan DATE 9/21/05
TEMPORARILY ABANDON CHANGE PLANS Image: Change Pull OR ALTER CASING Image: Change Pull Or ALTER CASING Pull Or ALTER CASING Pull Or ALTER CASING Image: Change Pull Or ALTER CASING Pull Or ALTER CASING Pull Or ALTER CASING Pull OF A STATURE Image: Change Pull Or ALTER CASING Pull Or ALTER CASING Pull OF A STATURE Pull OF A STATUR Pull OF A STATUR Pull OF A STATUR PULL OF A STATUR PUll OF A ST	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER: Il pertinent details, and give pertine tiple Completions: Attach wellbore of change the csg/cmt prod change the csg/cmt prod cl a 12 1/4" hole to csg; Cmt w/850 sks, cin cl a 7 7/8" hole to 8350 will be tied into surface best of my knowledge and belief. I bell, a general permit or an (attached) Production Analyst address: vsmith@texpetro.cc	P AND A Im dates, including estimated date diagram of proposed completion gram and // Od z 2230', Run rc to surface /, Run 5 1/2" ce csg. further certify that any pit or below- alternative OCD-approved plan [].
TEMPORARILY ABANDON CHANGE PLANS Image: Change Plans PULL OR ALTER CASING MULTIPLE COMPL Image: Complete Complet	COMMENCE DRILLING OPNS CASING/CEMENT JOB OTHER: Il pertinent details, and give pertine tiple Completions: Attach wellbore to change the csg/cmt proc change the csg/cmt proc clar 12 1/4" hole to csg; Cmt w/850 sks, cin clar 7 7/8" hole to 8350 will be tied into surface best of my knowledge and belief. I - , a general permit or an (attached) Production Analyst	P AND A Im dates, including estimated date diagram of proposed completion gram and //Od // Run 5 1/2" c csg. further certify that any pit or below- alternative OCD-approved plan