HOBBS OCD

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Operator Copy

OM B No. 1004-0137 Expires: March 31, 200

5. Lease Serial No.

JAN 1 0 2013

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

NM24683

6. If Indian, Allottce or Tribe Name

1. Type of Well Oil Well.	Gas Welli Other			8. Well Nan	
2. Name of Operator OXY USA I	, IC.	16	696	Feder 9. API We	I FBR #1
3a Address P.O. Box 50250 Midland, T.	X 79710	3b. Phone No. (include a 432-685-5717	rea code)	10. Field and	25-27266 Pool, or Exploratory Area Ridse Atoka (G
19.80 PSL 660 F1	PPROPRIATE BOX(ES) T			Lea	or Parish, State NM OTHER DATA
TYPE OF SUBMISSION		TYPE	OF ACTION		
Notice of Intent	Acidize Alter Casing Casing Repair Change Plans	Deepen Fracture Treat New Construction Plug and Abandon	Production (Stance) Reclamation Recomplete Temporarily Ab		Water Shut-Off Well Integrity Other

SEE ATTACHED

testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)								
David Stewart	Title	litle Regulatory Advisor						
Signature Un State THIS SPACE FOR FEDERA	Date AL OR	STAT	ပေါ် E OF		USET	APPI	ROVED	
						T		†
Approved by		Title				IDEC	2012	
Conditions of approval, if any, are attached. Approval of this notice does not wan certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to onduct operations thereon.		Office			BU	EAU OF LA	MOS ND MANAGEME	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for a States any false, fictitious or fraudulent statements or representations as to anyma	ny person tter within	knowing	ly and v	villfully t	make to	any departure	HELD OF TOE	he United

(Instructions on page 2)

determined that the site is ready for final inspection.)

Ohn

District I 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720 District II 81) S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III 1000 Rio Brazos Road, Aztec, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170

State of New Mexico

Energy, Minerals & Natural Resources Department OIL CONSERVATION DIVISION OCD 1220 South St. Francis Dr.

Santa Fe, NM 87505 **SEP 0 5 2012**

Form C-102 Revised August 1, 2011

Submit one copy to appropriate District Office

AMENDED REPORT

<u>District IV</u> 1220 S. St. Francis Dr. Phone: (505) 476-3460		6 3462		[M 8/303 SEP		LE	TUVIENUEL	/ REA OI	
		W	ELL LC	CATION	I AND ACR	EAGE DEDI	ATION PLA	T			
1	API Numbe	r		² Pool Code			I GOI IVA				
30-025	-2721	ele		72643	B∈	otleg Ride	e Atoka	a (Gas	•)		
4 Property	Code			-	⁵ Property N	Name	•		6 Well Numl	ber	
30462	25			4	edeval	EBR			1		
7 OGRID	⁷ OGRID No. ⁸ Operator Name								⁹ Elevation		
16694	694 OXY USA Inc.							3601.5			
					Surface I	Location					
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line Cou			
L	וין	225	33E		1980	south	660	west lea			
			и Bo	ttom Hole	e Location If	Different Fron	n Surface				
UL or lot no.	Section	Township	Range	Lot Idn	Fect from the	North/South line	Feet from the	East/We	est line	Count	
12 Dedicated Acre	s 13 Joint o	r Infill 14 C	onsolidation (Code 15 Ord	ler No.						
320	N)									
No allowable	will be see	signed to the	is complet	ion until all	interacte have l	neen consolidated	or a non etandar	rd unit has h	een approved	by the	

No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the division.

/ 				
110				17 OPERATOR CERTIFICATION
		,		I hereby certify that the information contained herein is true and complete
				to the best of my knowledge and belief, and that this organization either
i		,		owns a working interest or unleased mineral interest in the land including
(the proposed bottom hole location or has a right to drill this well at this
	!	1		location pursuant to a contract with an owner of such a mineral or working
	1			interest, or to a voluntary pooling agreement or a compulsory pooling
				order heretofore entered by the division.
\		<u> </u>		
		,		8012
				Signature Date
	2			David Stewert Reg. Adv. Printed Name devid stewert Boxy. com
	}	1		Printed Name
				1 11 -1 1000 604
: {	!			devil stewerter oxy, com
	:	\$		E-mail Address
1.		: [
				¹⁸ SURVEYOR CERTIFICATION
				I hereby certify that the well location shown on this
∦				
660 - 0 1		· (plat was plotted from field notes of actual surveys
III Ă		,		made by me or under my supervision, and that the
1		1		same is true and correct to the best of my belief.
				, , , , , , , , , , , , , , , , , , ,
		'		
				Date of Survey
 				Signature and Seal of Professional Surveyor:
ا او اا		1		
3				
<u>"</u>		!		
{ 				
	}			Certificate Number
V	and the same of th			
	ز اوند د د د د د د د د د د د د د د د د د د			

OXY USA Inc.

Federal EBR #1 - API No. 30-025-27266


TD-15270' PBTD-14765' Perfs-14039-14740' Mod DB Pkr-13991'

13-3/8" 54.5# csg @ 740' w/ 730sx, 17-1/2" hole, TOC-Surf-Circ 10-3/4" 40.5, 45.5, 51# csg @ 4974' w/ 2200sx, 12-1/4" hole, TOC-Surf-Circ 7-5/8" 26.4, 29.7# csg @ 12114' w/ 1050sx, 9-1/2" hole, TOC-6280'-Calc 5" 15# csg @ 11737-14813' w/ 700sx, 6-1/2" hole, TOC-11737'-Circ

Procedure:

- 1) Clean location & set anchors
- 2) RU DDPU, NU BOP. POOH w/existing tubing.
- 3) RIH & tag TOF @ +/- 13970' w/ Model DB Pkr @ 13991'. M&P 15sx CL H cmt from 13991-13845', WOC & Tag. Test casing after tag to 500# for 30 minutes.
- 4) PU prod BHA (profile nipple, packer, profile nipple, on/off tool), packer and TCP guns and RIH and set packer at 13,694'.
- 5) Disengage on/off tool and circulate packer fluid. Re-engage on/off tool and test backside to 1000psi. ND BOP and NU WH. RD WO Rig.
- 6) Swab well down with slickline and fire TCP guns and perforate interval from 13,744' 13,750' at 6 shots/ft
- 7) Monitor well and swab as needed if well does not flow.
- 8) Contact engineer with production results.

' OXY USA Inc. - Proposed Federal EBR #1 API No. 30-025-27266



15sx @ 13991-13845' WOC-Tag

Fish @ 13970-13992' w/ Mod DB Pkr @ 13991'

PB-14765'

OXY USA Inc. - Current Federal EBR #1 API No. 30-025-27266

17-1/2"-hole-@-740' 13-3/8" csg @ 740' w/ 730sx-TOC-Surf-Circ 12-1/4" hole @ 4974' 10-3/4" csg @ 4974' w/ 2200sx-TOC-Surf-Circ 9-1/2" hole @ 12114' 7-5/8" csg @ 12114' w/ 1050sx-TOC-6280'-Calc 6-1/2" hole @ 15270' 5" liner @ 11737-14813' w/700sx-TOC-11737'-Circ Perfs @ 14039-14042' Perfs @ 14432-14434' Perfs @ 14710-14740'

Fish @ 13970-13992' w/ Mod DB Pkr @ 13991'

PB-14765'

TD-15270'

Federal EBR #1
30-025-27266
OXY USA Inc.
December 11, 2012
Conditions of Approval

Notify BLM at 575-393-3612 a minimum of 24 hours prior to commencing work.

Work to be completed by March 11, 2012.

- 1. Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15. Exceptions to these restrictions may be granted by BLM's Johnny Chopp <jchopp@blm.gov> 575.234.2227 or Bob Ballard

 ballard@blm.gov> 575.234.5973.
- 2. Surface disturbance beyond the originally approved pad must have prior approval.
- 3. Closed loop system required.
- 4. Operator to have H2S monitoring equipment on location.
- 5. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above precharge. The pre-charge test shall follow requirements in Onshore Order #2.
- 6. The operator has two options for plugging back the Morrow formation.

a. Option 1:

1. Operator shall set solid cement plug across top of the Morrow formation, which is shown at 13,975' in the geological report. The minimum plug length is 240', however this would plug back into the location of the proposed perforations. Therefore, the plug shall be 146' in length and a minimum of 15 sacks of neat Class H cement. Plug to be set from approximately 13,991' to 13,845'. Tag at 13,845' or shallower. When plugging back the Atoka formation, however, the Operator shall add additional cement to increase the plug length to 240' or an addition of 10 sacks minimum. Tag required.

b. Option 2:

- 1. Operator shall set solid cement plug from TD to 13,925' using coil tubing to pass through the wedged packer. Tag required.
- 7. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 8. Subsequent sundry required detailing work done and completion report for new zone. Operator to include well bore schematic of current well condition when work is complete.

JAM 121112