TITED STATES JUTED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000 5. Lease Serial No. LC060881 6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No. SOUTH PEARL QUEEN	
Type of Well Gas Well Gas Well Gas Well Gas Well					8. Well Name and No. SOUTH PEARL QUEEN 15	
Name of Operator XERIC OIL & GAS CORPORATION Contact: ANGIE CRAWFORD E-Mail: ACrawford@xericoil.com					9. API Well No. 30-025-03324	
3n. Address P. O. BOX 352 MIDLAND, TX 79702	olude area code) 171 Ext: 235 48		10. Field and Pool, or Exploratory PEARL QUEEN			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State	
Sec 4 T20S R35E SESW 660FSL 1980FWL					LEA COUNTY, NM	
12. CHECK APPROPR	IATE BOX(ES) TO P	NDICATE N	ATURE OF N	IOTICE, R	BPORT, OR OTHER	DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
		Deepen		Production (Start/Resume)		□ Water Shut-Off
Notice of Intent Alter Casing		Fracture Treat		C Reclam	ation	Well Integrity
Subsequent Report Casing Repair		New Construction		Recomplete		Other
Final Abandonment Notice	Change Plans	🛛 Plug ar	d Abandon	🗖 Tempo	rarily Abandon	
	Convert to Injection	🗖 Plug B	ack	□ Water Disposal		
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reelamation, have been completed, and the operator has determined that the site is ready for final inspection.) 3/9/04 Spot 50 sx cmt @ 4947. WOC & tag @ 4802'. 3/10/04 Spot 25 sx cmt 3500-3400'. 3/11/04 Perf @ 2090'. Squeeze 75 sx cmt. WOC & tag @ 1900'. 3/12/04 Perf @ 2090'. Squeeze 40 sx cmt. WOC & tag @ 120'. Spot 10 sx @ 50' to surface. Install P&A marker, Circ. mud. Send Copy of Sundry Notice to NMOCD for approval.						
14. I hereby certify that the foregoing is true and correct. Electronic Submission #28948 verified by the BLM Well Information System For XERIC OIL & GAS CORPORATION, sent to the Hobbs. Name (Printed/Typed) W. KYLE LEWIS Title TREASURER						
Name (Printed/Typed) W. KYLE LEWIS			une IREAG	DUNEN		
Signature (Electronic Submission) Date 03/26/2004						
	THIS SPACE FOR	R FEDERAL	OR STATE	OFFICE	USE	
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject leas which would entitle the applicant to conduct operations thereon.			File		Date	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. States any false, fictitious or fraudulent states	. Section 1212, make it a ci		on knowingly ar		make to any department o	r agency of the United

** ODEDATOD CIDMITTED ** ODEDATOD CIDMITTED ** ODEDATOD CIRMITTED **