

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-23175
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NEW MEXICO S
8. Well Number #1
9. OGRID Number 272005
10. Pool name or Wildcat WEST SAWYER

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other **HOBBS OCD**

2. Name of Operator
TD & F, LLLP

3. Address of Operator
403 MADISON ARCH ROSWELL, NM 88201

FEB 13 2013

4. Well Location

Unit Letter H 660 feet from the EAST line and 1980 feet from the NORTH line
Section 32 Township 9-S Range 37-E NMPM LEA County

RECEIVED

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

REFER TO PREVIOUS WORK ATTEMPTS TO ALIGN CASING.

EST RATE

150

1. MIRU PULLING UNIT. RIH W/ PKR AND TBG TO 2900'. SQZ PARTED 4 1/2" CSG @ 3157' W/ 20 SXS CMT.
2. WOC AND TAG NO DEEPER 3057'. CIRC CSG W/ MLF.
3. PERF @ 2200'. SQZ W/ 25 SXS CMT. WOC AND TAG.
4. PERF @ 519', CIRC CMT TO SURFACE INSIDE AND OUT.
5. CUT OFF WELLHEAD AND INSTALL BELOW GRADE MARKER, CUT ANCHORS AND CLEAN LOC.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

DATE

2/13/2013

Type or print name

E-mail address:

PHONE:

575-370-1434

For State Use Only

APPROVED BY:

TITLE

DATE

2/13/2013

Conditions of Approval (if any):

2-M

Chm

T D E F, L L L P
NEW MEXICO S #1
30-025-23175
PRESENT

