
Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103	
Dinament (575) 202 (161 Ene	rgy, Minerals and Natural Resources	October 13, 2009 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240BBS OCD District II – (575) 748-1283	CONCEDIATION DIVICION	30-025-38279	
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 8 本均 1 2 2013	Santa Fe, NM 87505	STATE XX FEE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa re, NW 67505	6. State Oil & Gas Lease No.	
87505 DECENTED		LG - 2616	
SUNDRY NOTICES AND (DO NOT USE THIS FORM FOR PROPOSALS TO DI		7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FO		Amoco State	
PROPOSALS.)  1. Type of Well: Oil Well Gas Well Other Dry Hole		8. Well Number 2	
2. Name of Operator Primero Operating, Inc.		9. OGRID Number 018100	
3. Address of Operator		10. Pool name or Wildcat	
PO Box 1433,	Roswell, NM 88202-1433	Maljamar, Grayburg, SA	
4. Well Location			
Unit Letter $\frac{I}{}$ : $\frac{1982}{}$ feet from the $\frac{South}{}$ line and $\frac{510}{}$ feet from the $\frac{E}{}$ line			
Section 36	Township 16S Range 32E	NMPM Lea County	
11. Elev 4249	vation (Show whether DR, RKB, RT, GR, etc.		
4249	G G L	4 . ** . * *	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
	AND ABANDON REMEDIAL WOR	<u> </u>	
	E PLANS		
PULL OR ALTER CASING   MULTIF	PLE COMPL CASING/CEMEN	T JOB 🔲	
DOWNHOLE COMMINGLE		·	
OTHER:	OTHER: Cor.	rect Dry Hole Marker	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion	L.		
Persuant to Letter of Violat	ion letter Dated 3/23/2011 we	have added the API# to the .	
dry hole marker.			
<del>-</del>			
	NOTE: The Letter of Violation letter indicates that the dry hole marker is on the wrong hole but it is actaully on the correct hole. There may be some confusion based		
note but it is actaur.	ly on the correct hole. There		
on two different surve			
on two different surve			
on two different surve			
on two different surve			
on two different surve			
	eys.		
on two different surve			
	eys.		
Spud Date:	Rig Release Date:	may be some confusion based	
	Rig Release Date:	may be some confusion based	
Spud Date:  I hereby certify that the information above is to the second	Rig Release Date:	e may be some confusion based	
Spud Date:  I hereby certify that the information above is to signature.	Rig Release Date:  rue and complete to the best of my knowleds  TITLE  President	e may be some confusion based  e and belief.  DATE 2/8/2013	
Spud Date:  I hereby certify that the information above is to signature.  SIGNATURE  Type or print name Phelps White	Rig Release Date:	e may be some confusion based  e and belief.  DATE 2/8/2013	
Spud Date:  I hereby certify that the information above is to signature.	Rig Release Date:  rue and complete to the best of my knowledg  TITLE  President  E-mail address:  pwiv@ziane	may be some confusion based  e and belief.  DATE 2/8/2013  t.com PHONE: 575 626 7660	
Spud Date:  I hereby certify that the information above is to signature.  SIGNATURE  Type or print name Phelps White	Rig Release Date:  rue and complete to the best of my knowledg  TITLE  President  E-mail address:  pwiv@ziane	may be some confusion based  e and belief.  DATE 2/8/2013  t.com PHONE: 575 626 7660	
Spud Date:  I hereby certify that the information above is to signature.  SIGNATURE  Type or print name Phelps White  For State Use Only	Rig Release Date:  rue and complete to the best of my knowledg  TITLE  President  E-mail address:  pwiv@ziane	e may be some confusion based  ge and belief.  DATE 2/8/2013	

PRIMERO OPERATING INC PO BOX 1433 ROSWELL, NM 88202



Anchor removed 2/8/13

NOTE: Letter of Violation dated 3/23/13 stated that the markers were on the wrong locations. The markers are on the correct locations the #1 well IS NE of the #2 well. It is confusing due to different surveys on different dates.

COMPLIANCE OFFICER