Submit 3 copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

ISTRICT I			
	OIL CONSERV	ATION DIVISION	WELL API NO.
O. Box 1980, Hobbs, NM 88240		Box 2088	30-025-31482
STRICT II	Santa Fe New	Mexico 87504-2088	5. Indicate Type of Lease
D. Box Drawer DD, Artesia, NM 882	10		STATE ✓ FEE 🗌
STRICT III	_		6. State Oil / Gas Lease No.
00 Rio Brazos Rd., Aztec, NM 87410			B9613
SUNDRY N (DO NOT USE THIS FORM FOR PI	OTICES AND REPORTS O		
	SERVOIR. USE "APPLICATIO		7. Lease Name or Unit Agreement Name
(FORI	M C-101) FOR SUCH PROPOS	SALS.	WEST DOLLARHIDE DRINKARD UNIT
	AS OTHER		
Name of Operator CHEVRON	N USA INC		8. Well No. 113
Address of Operator 15 SMITH	RD, MIDLAND, TX 79705		Pool Name or Wildcat DOLLARHIDE TUBB DRINKARD
Well Location			
Unit Letter M:	136 Feet From The	SOUTH Line and 1246	Feet From The <u>WEST</u> Line
Section 32	Township24S	Range38EN	MPM <u>LEA</u> COUNTY
	10. Elevation (Show whether	DF, RKB, RT,GR, etc.) 3140'	
		ate Nature of Notice, Repor	t, or Other Data
NOTICE OF INTENT	TON TO:	S	UBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	✓ ALTERING CASING
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OF	PERATION PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEME	ENT.JOB
OTHER:			ASING LEAK - TEMPORARILY ABANDON
Describe Proposed or Completed	Operations (Clearly state all pe		dates, including estimated date of starting any
proposed work) SEE RULE 1103. -31-05: MIRU PU. TIH W/SPEAR 0 9-01-05: CUT OVER FISH. -02-05: LATCH ONTO TBG. PUH W -06-05: TIH W/CIBP & SET @ 6215 -07-05: CIRC HOLE CLEAN W/PKR	CABLE GRAB, BUMP SUB, 23 V/FISH. 5'. TIH W/23/8" TBG TO 6215. R FLUID. TEST CSG TO 500# ART. NO BLEED. OCD WITNE	TAG CIBP. PU 30'.	dates, including estimated date of starting any /EL. CUT ON CABLE.
 Describe Proposed or Completed or proposed work) SEE RULE 1103. 3-31-05: MIRU PU. TIH W/SPEAR 0. 39-01-05: CUT OVER FISH. 39-02-05: LATCH ONTO TBG. PUH W. 39-06-05: TIH W/CIBP & SET @ 6215. 39-07-05: CIRC HOLE CLEAN W/PKF. RUN MIT - 500# FOR 30 MIN. W/CH. WELL IS TEMPORARILY ABANDON. 	CABLE GRAB, BUMP SUB, 23 V/FISH. 5'. TIH W/2 3/8" TBG TO 6215. R FLUID. TEST CSG TO 500# ART. NO BLEED. OCD WITNE	TAG CIBP. PU 30'. NO BLEED.	dates, including estimated date of starting any /EL. CUT ON CABLE.
proposed work) SEE RULE 1103. 3-31-05: MIRU PU. TIH W/SPEAR (19-01-05: CUT OVER FISH. 1-02-05: LATCH ONTO TBG. PUH W 1-06-05: TIH W/CIBP & SET @ 6215 1-07-05: CIRC HOLE CLEAN W/PKF RUN MIT - 500# FOR 30 MIN. W/CH, VELL IS TEMPORARILY ABANDON	CABLE GRAB, BUMP SUB, 23 V/FISH. 5'. TIH W/23/8" TBG TO 6215. R FLUID. TEST CSG TO 500# ART. NO BLEED. OCD WITNE	TAG CIBP. PU 30'. NO BLEED.	dates, including estimated date of starting any /EL. CUT ON CABLE. COPY OF CHART ATTACHED)
proposed work) SEE RULE 1103. -31-05: MIRU PU. TIH W/SPEAR (19-01-05: CUT OVER FISH02-05: LATCH ONTO TBG. PUH W -06-05: TIH W/CIBP & SET @ 6215 -07-05: CIRC HOLE CLEAN W/PKF RUN MIT - 500# FOR 30 MIN. W/CH, VELL IS TEMPORARILY ABANDON	CABLE GRAB, BUMP SUB, 23 V/FISH. 5'. TIH W/2 3/8" TBG TO 6215. R FLUID. TEST CSG TO 500# ART. NO BLEED. OCD WITNE IED. This Approval of Te Abandonment Expi	emporary 9-17-10	dates, including estimated date of starting any /EL. CUT ON CABLE. COPY OF CHART ATTACHED)

OC FIELD REPRESENTATIVE INSTAFF MANAGER

