	State of New Mexico			/ Form C-103
District I UORRS OC	Energy, Minerals and Natural Ro	esources		October 13, 2009
Office  District I  1625 N. French Dr., Hobbs, NM 88240  District II		V <sub>2</sub>	VELL API NO. 0-025-34056	
District II 1301 W. Grand Ave., Artesia, NM 88210 27 2 District III	NOTE CONSERVATION DIV	ISION $\frac{3}{5}$	. Indicate Type of Lea	920
District III FEB 2 1 2	1220 South St. Francis I	Or.	STATE	FEE 📝
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6	. State Oil & Gas Leas	
1220 S. St. Francis Dr., Santa Fe, NM RECEIVE 87505	ED .			
SUNDRY NOTICES	AND REPORTS ON WELLS		. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS DIFFERENT RESERVOIR, USE "APPLICATION"	FO DRILL OR TO DEEPEN OR PLUG BAC N. FOR DEDMIT!! (FORM C-101) FOR SHO			
PROPOSALS.)	N FOR PERMIT (FORM C-101) FOR SUC	_5	elby Maveety	
	Well 🗌		. Well Number 4	
2. Name of Operator Apache Corp.		9	. OGRID Number	873 ~
3. Address of Operator		1	0. Pool name or Wilde	cat
P O box Drawer D Monument NM 8826	5	N	Ionument Abo	
4. Well Location				
Unit LetterN:_97	feet from theSouth_	line and	1650fe	et from the
Westline				
Section 35	Township 19S Ra	nge 36E	NMPM	Lea County
	Elevation (Show whether DR, RKB,	RT, GR, etc.)		
12 Charle Anne	opriate Box to Indicate Nature	of Notice Pa	onart or Other Data	
12. Clieck Apple	opriate Box to indicate Nature	of Notice, Re	port of Other Data	
NOTICE OF INTEN	ITION TO:	SUBSE	<b>EQUENT REPOR</b>	RT OF:
	JG AND ABANDON 🔲 📗 REN	IEDIAL WORK	☐ ALTE	ERING CASING
		MENCE DRILLI		ID A
<del></del>	LTIPLE COMPL   CAS	ING/CEMENT J	OB 🔲	
DOWNHOLE COMMINGLE		•		
OTHER:			- d TA - 4-4	
OTTEN.		ER: Exte	nd TA status	
				luding estimated date
13. Describe proposed or completed of starting any proposed work).	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For	ent details, and g	ve pertinent dates, inc	
13. Describe proposed or completed	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For	ent details, and g	ve pertinent dates, inc	
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For	ent details, and g	ve pertinent dates, inc	
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion.	ent details, and g Multiple Comp	ve pertinent dates, inc etions: Attach wellbo	re diagram of
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13  MIRU Gandy truck # 610 and pressure the	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion. e casing to 530 psi. Held the pressur	ent details, and g Multiple Comp	ve pertinent dates, inc etions: Attach wellbo	re diagram of
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion. e casing to 530 psi. Held the pressur	ent details, and g Multiple Comp	ve pertinent dates, inc etions: Attach wellbo	re diagram of
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13  MIRU Gandy truck # 610 and pressure the	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion.  e casing to 530 psi. Held the pressur lests an extension of TA status.	ent details, and g Multiple Comp e and recorded o	ve pertinent dates, inc etions: Attach wellbo n a chart for 32 minute	re diagram of es.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13  MIRU Gandy truck # 610 and pressure the	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion.  e casing to 530 psi. Held the pressur lests an extension of TA status.	ent details, and g Multiple Comp e and recorded o	ve pertinent dates, inc etions: Attach wellbo n a chart for 32 minute	re diagram of es.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13  MIRU Gandy truck # 610 and pressure the	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion.  e casing to 530 psi. Held the pressur lests an extension of TA status.	ent details, and g Multiple Comp e and recorded o	ve pertinent dates, inc etions: Attach wellbo	re diagram of es.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13  MIRU Gandy truck # 610 and pressure the	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion.  e casing to 530 psi. Held the pressur lests an extension of TA status.	ent details, and g Multiple Comp e and recorded o	ve pertinent dates, inc etions: Attach wellbo n a chart for 32 minute	re diagram of es.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13  MIRU Gandy truck # 610 and pressure the	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion.  e casing to 530 psi. Held the pressur lests an extension of TA status.	ent details, and g Multiple Comp e and recorded o	ve pertinent dates, inc etions: Attach wellbo n a chart for 32 minute	re diagram of es.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13  MIRU Gandy truck # 610 and pressure the	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion.  e casing to 530 psi. Held the pressur lests an extension of TA status.	ent details, and g Multiple Comp e and recorded o	ve pertinent dates, inc etions: Attach wellbo n a chart for 32 minute	re diagram of es.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13  MIRU Gandy truck # 610 and pressure the	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion.  e casing to 530 psi. Held the pressur lests an extension of TA status.	ent details, and g Multiple Comp e and recorded o	ve pertinent dates, inc etions: Attach wellbo n a chart for 32 minute	re diagram of es.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13 MIRU Gandy truck # 610 and pressure the The pressure dropped 30 psi. Apache-required the pressure dropped 30 psi.	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion.  e casing to 530 psi. Held the pressurests an extension of TA status.	ent details, and g Multiple Comp e and recorded o	ve pertinent dates, inc etions: Attach wellbo n a chart for 32 minute	re diagram of es.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13  MIRU Gandy truck # 610 and pressure the	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion.  e casing to 530 psi. Held the pressur lests an extension of TA status.	ent details, and g Multiple Comp e and recorded o	ve pertinent dates, inc etions: Attach wellbo n a chart for 32 minute	re diagram of es.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13 MIRU Gandy truck # 610 and pressure the The pressure dropped 30 psi. Apache-required the pressure dropped 30 psi.	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion.  e casing to 530 psi. Held the pressurests an extension of TA status.	ent details, and g Multiple Comp e and recorded o	ve pertinent dates, inc etions: Attach wellbo n a chart for 32 minute	re diagram of es.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13 MIRU Gandy truck # 610 and pressure the The pressure dropped 30 psi. Apache-requ	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion.  e casing to 530 psi. Held the pressurests an extension of TA status.  Rig Release Date:	ent details, and g Multiple Comple e and recorded o This Approv Abandonme	ve pertinent dates, inc etions: Attach wellbo n a chart for 32 minute al of Temporary nt Expires	re diagram of es.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13 MIRU Gandy truck # 610 and pressure the The pressure dropped 30 psi. Apache-required the pressure dropped 30 psi.	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion.  e casing to 530 psi. Held the pressurests an extension of TA status.  Rig Release Date:	ent details, and g Multiple Comple e and recorded o This Approv Abandonme	ve pertinent dates, inc etions: Attach wellbo n a chart for 32 minute al of Temporary nt Expires	re diagram of es.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13 MIRU Gandy truck # 610 and pressure the The pressure dropped 30 psi. Apache-requ	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion.  e casing to 530 psi. Held the pressurests an extension of TA status.  Rig Release Date:	ent details, and g Multiple Comple e and recorded o This Approv Abandonme	ve pertinent dates, inc etions: Attach wellbo n a chart for 32 minute al of Temporary nt Expires	re diagram of es.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13 MIRU Gandy truck # 610 and pressure the The pressure dropped 30 psi. Apache-requ	operations. (Clearly state all pertine SEE RULE 19.15.7.14 NMAC. For etion.  e casing to 530 psi. Held the pressur lests an extension of TA status.  Rig Release Date:	ent details, and g Multiple Comple e and recorded o This Approv Abandonme	ve pertinent dates, inc etions: Attach wellbo n a chart for 32 minute al of Temporary nt Expires	re diagram of es.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13 MIRU Gandy truck # 610 and pressure the The pressure dropped 30 psi. Apache required the psi dropped 30 psi d	Rig Release Date:  TITLEInstrume	ent details, and g Multiple Comple e and recorded of This Approv Abandonme  my knowledge and nt Tech	ve pertinent dates, inc etions: Attach wellbo n a chart for 32 minute al of Temporary nt Expires	27-2015 2-27-13
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13  MIRU Gandy truck # 610 and pressure the The pressure dropped 30 psi. Apache required the psi. Apache require	Rig Release Date:  TITLEInstrume	ent details, and g Multiple Comple e and recorded of This Approv Abandonme  my knowledge and nt Tech	ve pertinent dates, inc etions: Attach wellbo n a chart for 32 minute al of Temporary nt Expires	27-2015 2-27-13
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13 MIRU Gandy truck # 610 and pressure the The pressure dropped 30 psi. Apache required the psi dropped 30 psi d	Rig Release Date:  TITLEInstrume	ent details, and g Multiple Comple e and recorded of This Approv Abandonme  my knowledge and nt Tech	n a chart for 32 minute  al of Temporary  nt Expires  DATE  eccorp.com_ PHONE:	27-2015 2-27-13
13. Describe proposed or completed of starting any proposed work). proposed completion or recomple 2/27/13  MIRU Gandy truck # 610 and pressure the The pressure dropped 30 psi. Apache required the psi. Apache require	Rig Release Date:  TITLEInstrume	ent details, and g Multiple Comple e and recorded of This Approv Abandonme  my knowledge and nt Tech	n a chart for 32 minute  al of Temporary  nt Expires  DATE  eccorp.com_ PHONE:	27-2015 2-27-13
13. Describe proposed or completed of starting any proposed work). proposed completion or recompleted 2/27/13  MIRU Gandy truck # 610 and pressure the The pressure dropped 30 psi. Apache requirements of the psi. Apache require	Rig Release Date:  Bis true and complete to the best of TITLE Instrume  E-mail address: _JE	ent details, and g Multiple Comple e and recorded of This Approv Abandonme  my knowledge and nt Tech	n a chart for 32 minute  al of Temporary  nt Expires  DATE  eccorp.com_ PHONE:	27-2015 2-27-13

