Submit 1 Copy To Appropriate Distr HOBBS OCD State of New Mexico Office	Form C-103
Energy Minerals and Natural Resources	Revised August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88340AR 0 6 2013 District II - (575) 748-1283	30-025-05366
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 874 RECEIVED District IV – (505) 476-3460 ! 1220 South St. Francis Dr. Santa Fe, NM 87505	STATE FEE
(500) 170 5 1111	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	8-7896
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	State O
PROPOSALS.)	0 W.W.Y. L. #10
1. Type of Well: Oil Well X Gas Well Other	8. Well Number#10
2. Name of Operator Vanguard Permian LLC	9. OGRID Number 258350
3. Address of Operator	10. Pool name or Wildcat
1209 south Main Lovington, NM 88260	Lovington Abo
4. Well Location	le
Unit Letter L: 440 feet from the South line and 3080 feet from the	
East N line	
Section 31 Township 16S Range 37E	NMPM LEA County
11. Elevation (Show whether DR, RKB, RT, GR, etc.,	
3833DF	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A	
PULL OR ALTER CASING	T JOB 🔲
DOWNHOLE COMMINGLE []	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
1 DH 21 OVD - 1 - 0 0000 - 1 - 1 - 41 - 0 0 0000 0450 0 - 21	
 RIH with CIBP and set @ 8290' above lower Abo perfs @ 8300-8450'. Cap with cement. RIH and perforate upper Abo from 8138-8254' 	
3. RIH with packer and set @ 8050'.	
4. Acidize upper Abo perfs with 2000 gals acid.	
Swab test upper Abo perfs to attain economics.	
6. Start pumping Upper Abo perfs @ State L "A" tank battery.	
7. Return well to active status from shut in status.	
,	
Spud Date: Rig Release	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Thereby certify that the another above is true and complete to the best of my knowledge and benefit.	
SIGNATURE TITLE Engineer	DATE 03/06/20/3
CAR I I Do	
Type or print name C.M. Doodworth, 1. E-mail address: Mb/oodworth PHONE: 432-362-2209	
For State Use Only Petroleum Engineer NAR 0 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	
APPROVED BY: TITLE	DATE MAK V 7 2010
Conditions of Approval 4 any):	