Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	June 19, 2008
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-025-40655
	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1 000 Rio Brazos Rd Aztec NM 8741 0	BS OCD 1220 South St. Francis Dr. Santa Fe. NM 87505	STATE 🛛 FEE 🗌
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505 FEB	2 0 2013	VB-1296
SUNDRY NOTICE	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSAL	S TO DRILL OR TO DEEPEN OR PLUG BACK TO A LONE PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	· <u> </u>	Trigger State
	s Well Other	8. Well Number 1
2. Name of Operator	and Companyion	9. OGRID Number 013837
3. Address of Operator	ergy Corporation	10. Pool Name or Wildcat
·	Artesia, NM 88210	WC-025 G-06 S183518A; Bone Spring
4. Well Location	Altesia, INIVI 88210	WC-023 G-00 3163316A, Bolic Spring
1	330 feet from the North line and	1650 feet from the East line
Section 13	Township 18S Range 34E	NMPM County Lea
School	11. Elevation (Show whether DR, RKB, RT, GR ea	1 title to
	3982' GR	
The state of the s		Ind. sacrace
12. Check App	propriate Box to Indicate Nature of Notice	e, Report or Other Data
**		•
NOTICE OF INTE		BSEQUENT REPORT OF:
<u>=</u>	PLUG AND ABANDON REMEDIALWO	DRK ☐ ALTERING CASING ☐ PRILLING OPNS.☐ PAND A ☐
<u> </u>		***
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	INT JOB
DOMINIOLE GOIMMINIOLE		
OTHER:	OTHER:	Completion 🔀
13. Describe proposed or complete	d operations. (Clearly state all pertinent details, a	and give pertinent dates, including estimated date
13. Describe proposed or complete of starting any proposed work	d operations. (Clearly state all pertinent details, a	
13. Describe proposed or complete of starting any proposed work or recompletion.	ed operations. (Clearly state all pertinent details, a). SEE RULE 1103. For Multiple Completions: A	and give pertinent dates, including estimated date
13. Describe proposed or complete of starting any proposed work or recompletion. 12/10/2012 Perforated 9025-9141	ed operations. (Clearly state all pertinent details, at). SEE RULE 1103. For Multiple Completions: At 40 holes.	and give pertinent dates, including estimated date
13. Describe proposed or complete of starting any proposed work of-recompletion. 12/10/2012 Perforated 9025-9141 12/11/2012 Acidized w/ 2250 gals	ed operations. (Clearly state all pertinent details, at). SEE RULE 1103. For Multiple Completions: At 40 holes.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or complete of starting any proposed work of-recompletion. 12/10/2012 Perforated 9025-9141 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15%	od operations. (Clearly state all pertinent details, and operations.). SEE RULE 1103. For Multiple Completions: And holes. Solution 15% HCL. HCL Acid, 190 bbls 20# Linear Gel, 2147	Attach wellbore diagram of proposed completion 7.9 bbls 20# Borate, 112,341# Whitesand
13. Describe proposed or complete of starting any proposed work of-recompletion. 12/10/2012 Perforated 9025-9141 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug	od operations. (Clearly state all pertinent details, at). SEE RULE 1103. For Multiple Completions: At , 40 holes. Solve 15% HCL. HCL Acid, 190 bbls 20# Linear Gel, 2147 set @ 9,000'. Perforated 8894-8923', 32 h	Attach wellbore diagram of proposed completion 7.9 bbls 20# Borate, 112,341# Whitesand holes. Frac w/ 40.4 bbls 15% HCL Acid,
13. Describe proposed or complete of starting any proposed work of-recompletion. 12/10/2012 Perforated 9025-9141 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b	od operations. (Clearly state all pertinent details, and operations.). SEE RULE 1103. For Multiple Completions: And holes. Solution 15% HCL. HCL Acid, 190 bbls 20# Linear Gel, 2147	Attach wellbore diagram of proposed completion 7.9 bbls 20# Borate, 112,341# Whitesand holes. Frac w/ 40.4 bbls 15% HCL Acid,
13. Describe proposed or complete of starting any proposed work of-recompletion. 12/10/2012 Perforated 9025-9141 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out.	d operations. (Clearly state all pertinent details, a). SEE RULE 1103. For Multiple Completions: Adv. 40 holes. 5: 15% HCL. HCL Acid, 190 bbls 20# Linear Gel, 2147 set @ 9,000'. Perforated 8894-8923', 32 hbls 20# Borate, 122,622# Whitesand 20/4	Attach wellbore diagram of proposed completion 7.9 bbls 20# Borate, 112,341# Whitesand holes. Frac w/ 40.4 bbls 15% HCL Acid,
13. Describe proposed or complete of starting any proposed work of recompletion. 12/10/2012 Perforated 9025-9141' 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out. 2/7/2013 Perforated 8223-8325.5',	d operations. (Clearly state all pertinent details, a partial of the completions: A partial of t	Attach wellbore diagram of proposed completion 7.9 bbls 20# Borate, 112,341# Whitesand holes. Frac w/ 40.4 bbls 15% HCL Acid,
13. Describe proposed or complete of starting any proposed work of-recompletion. 12/10/2012 Perforated 9025-9141' 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out. 2/7/2013 Perforated 8223-8325.5', 2/8/2013 Acidize w/ 1950 gals 15'	d operations. (Clearly state all pertinent details, a). SEE RULE 1103. For Multiple Completions: Adv. 40 holes. 1, 40 holes. 1, 40 holes. 1, 40 holes. 2, 15% HCL. 2, HCL Acid, 190 bbls 20# Linear Gel, 2147, set @ 9,000'. Perforated 8894-8923', 32 holes 20# Borate, 122,622# Whitesand 20/4, 58 holes. Set RBP @ 8414'. 2, 58 holes. Set RBP @ 8414'.	Attach wellbore diagram of proposed completion 7.9 bbls 20# Borate, 112,341# Whitesand noles. Frac w/ 40.4 bbls 15% HCL Acid, 0, 37,193# SLC 20/40.
13. Describe proposed or complete of starting any proposed work of-recompletion. 12/10/2012 Perforated 9025-9141' 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out. 2/7/2013 Perforated 8223-8325.5', 2/8/2013 Acidize w/ 1950 gals 15'	d operations. (Clearly state all pertinent details, a partial of the completions: A partial of t	Attach wellbore diagram of proposed completion 7.9 bbls 20# Borate, 112,341# Whitesand noles. Frac w/ 40.4 bbls 15% HCL Acid, 0, 37,193# SLC 20/40.
13. Describe proposed or complete of starting any proposed work of-recompletion. 12/10/2012 Perforated 9025-9141' 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out. 2/7/2013 Perforated 8223-8325.5', 2/8/2013 Acidize w/ 1950 gals 15'	d operations. (Clearly state all pertinent details, a). SEE RULE 1103. For Multiple Completions: Adv. 40 holes. 1, 40 holes. 1, 40 holes. 1, 40 holes. 2, 15% HCL. 2, HCL Acid, 190 bbls 20# Linear Gel, 2147, set @ 9,000'. Perforated 8894-8923', 32 holes 20# Borate, 122,622# Whitesand 20/4, 58 holes. Set RBP @ 8414'. 2, 58 holes. Set RBP @ 8414'.	Attach wellbore diagram of proposed completion 7.9 bbls 20# Borate, 112,341# Whitesand noles. Frac w/ 40.4 bbls 15% HCL Acid, 0, 37,193# SLC 20/40.
13. Describe proposed or complete of starting any proposed work of-recompletion. 12/10/2012 Perforated 9025-9141' 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out. 2/7/2013 Perforated 8223-8325.5', 2/8/2013 Acidize w/ 1950 gals 15'	d operations. (Clearly state all pertinent details, a). SEE RULE 1103. For Multiple Completions: Adv. 40 holes. 1, 40 holes. 1, 40 holes. 1, 40 holes. 2, 15% HCL. 2, HCL Acid, 190 bbls 20# Linear Gel, 2147, set @ 9,000'. Perforated 8894-8923', 32 holes 20# Borate, 122,622# Whitesand 20/4, 58 holes. Set RBP @ 8414'. 2, 58 holes. Set RBP @ 8414'.	Attach wellbore diagram of proposed completion 7.9 bbls 20# Borate, 112,341# Whitesand noles. Frac w/ 40.4 bbls 15% HCL Acid, 0, 37,193# SLC 20/40.
13. Describe proposed or complete of starting any proposed work; of-recompletion. 12/10/2012 Perforated 9025-9141; 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out. 2/7/2013 Perforated 8223-8325.5', 2/8/2013 Acidize w/ 1950 gals 15; 2/12/2013 Release RBP. RIH w/	d operations. (Clearly state all pertinent details, a). SEE RULE 1103. For Multiple Completions: Ad holes. 4, 40 holes. 5 15% HCL. HCL Acid, 190 bbls 20# Linear Gel, 2147 set @ 9,000'. Perforated 8894-8923', 32 hbls 20# Borate, 122,622# Whitesand 20/4, 58 holes. Set RBP @ 8414'. 76 HCL. 77 HCL. 78 HCL. 78 HCL. 78 HCL. 78 HCL.	Attach wellbore diagram of proposed completion 2.9 bbls 20# Borate, 112,341# Whitesand noles. Frac w/ 40.4 bbls 15% HCL Acid, 0, 37,193# SLC 20/40.
13. Describe proposed or complete of starting any proposed work; of-recompletion. 12/10/2012 Perforated 9025-9141' 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out. 2/7/2013 Perforated 8223-8325.5', 2/8/2013 Acidize w/ 1950 gals 15' 2/12/2013 Release RBP. RIH w/	d operations. (Clearly state all pertinent details, a). SEE RULE 1103. For Multiple Completions: Adv. 40 holes. 1, 40 holes. 1, 40 holes. 1, 40 holes. 2, 15% HCL. 2, HCL Acid, 190 bbls 20# Linear Gel, 2147, set @ 9,000'. Perforated 8894-8923', 32 holes 20# Borate, 122,622# Whitesand 20/4, 58 holes. Set RBP @ 8414'. 2, 58 holes. Set RBP @ 8414'.	Attach wellbore diagram of proposed completion 7.9 bbls 20# Borate, 112,341# Whitesand noles. Frac w/ 40.4 bbls 15% HCL Acid, 0, 37,193# SLC 20/40.
13. Describe proposed or complete of starting any proposed work; of-recompletion. 12/10/2012 Perforated 9025-9141; 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out. 2/7/2013 Perforated 8223-8325.5', 2/8/2013 Acidize w/ 1950 gals 15; 2/12/2013 Release RBP. RIH w/	d operations. (Clearly state all pertinent details, a). SEE RULE 1103. For Multiple Completions: Ad holes. 4, 40 holes. 5 15% HCL. HCL Acid, 190 bbls 20# Linear Gel, 2147 set @ 9,000'. Perforated 8894-8923', 32 hbls 20# Borate, 122,622# Whitesand 20/4, 58 holes. Set RBP @ 8414'. 76 HCL. 77 HCL. 78 HCL. 78 HCL. 78 HCL. 78 HCL.	Attach wellbore diagram of proposed completion 2.9 bbls 20# Borate, 112,341# Whitesand noles. Frac w/ 40.4 bbls 15% HCL Acid, 0, 37,193# SLC 20/40.
13. Describe proposed or complete of starting any proposed work; of-recompletion. 12/10/2012 Perforated 9025-9141' 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out. 2/7/2013 Perforated 8223-8325.5', 2/8/2013 Acidize w/ 1950 gals 15' 2/12/2013 Release RBP. RIH w/ Spud Date: 11/5/2012	d operations. (Clearly state all pertinent details, a). SEE RULE 1103. For Multiple Completions: Ad holes. 4, 40 holes. 5 15% HCL. HCL Acid, 190 bbls 20# Linear Gel, 2147 set @ 9,000'. Perforated 8894-8923', 32 hbls 20# Borate, 122,622# Whitesand 20/4, 58 holes. Set RBP @ 8414'. 76 HCL. 77 HCL. 78 HCL. 78 HCL. 78 HCL. 78 HCL.	Attach wellbore diagram of proposed completion 2.9 bbls 20# Borate, 112,341# Whitesand holes. Frac w/ 40.4 bbls 15% HCL Acid, 0, 37,193# SLC 20/40. 2.1/2 x 2 x 24' pump.
13. Describe proposed or complete of starting any proposed work; of-recompletion. 12/10/2012 Perforated 9025-9141' 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out. 2/7/2013 Perforated 8223-8325.5', 2/8/2013 Acidize w/ 1950 gals 15' 2/12/2013 Release RBP. RIH w/ Spud Date: 11/5/2012	d operations. (Clearly state all pertinent details, a). SEE RULE 1103. For Multiple Completions: A , 40 holes. 5 15% HCL. HCL Acid, 190 bbls 20# Linear Gel, 2147 set @ 9,000'. Perforated 8894-8923', 32 hols 20# Borate, 122,622# Whitesand 20/4 , 58 holes. Set RBP @ 8414'. 6 HCL. 285jts 2 7/8", L-80, 6.5# tubing @ 9147'. Rig Release Date:	Attach wellbore diagram of proposed completion 2.9 bbls 20# Borate, 112,341# Whitesand holes. Frac w/ 40.4 bbls 15% HCL Acid, 0, 37,193# SLC 20/40. 2.1/2 x 2 x 24' pump.
13. Describe proposed or complete of starting any proposed work of recompletion. 12/10/2012 Perforated 9025-9141' 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out. 2/7/2013 Perforated 8223-8325.5', 2/8/2013 Acidize w/ 1950 gals 15' 2/12/2013 Release RBP. RIH w/ Spud Date: 11/5/2012	d operations. (Clearly state all pertinent details, a). SEE RULE 1103. For Multiple Completions: A , 40 holes. 1, 40 holes. 1	Attach wellbore diagram of proposed completion 7.9 bbls 20# Borate, 112,341# Whitesand holes. Frac w/ 40.4 bbls 15% HCL Acid, 0, 37,193# SLC 20/40. 2 1/2 x 2 x 24' pump. 11/24/2012 dge and belief.
13. Describe proposed or complete of starting any proposed work; of-recompletion. 12/10/2012 Perforated 9025-9141' 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out. 2/7/2013 Perforated 8223-8325.5', 2/8/2013 Acidize w/ 1950 gals 15' 2/12/2013 Release RBP. RIH w/ Spud Date: 11/5/2012	d operations. (Clearly state all pertinent details, a). SEE RULE 1103. For Multiple Completions: A , 40 holes. 5 15% HCL. HCL Acid, 190 bbls 20# Linear Gel, 2147 set @ 9,000'. Perforated 8894-8923', 32 hols 20# Borate, 122,622# Whitesand 20/4 , 58 holes. Set RBP @ 8414'. 6 HCL. 285jts 2 7/8", L-80, 6.5# tubing @ 9147'. Rig Release Date:	Attach wellbore diagram of proposed completion 2.9 bbls 20# Borate, 112,341# Whitesand holes. Frac w/ 40.4 bbls 15% HCL Acid, 0, 37,193# SLC 20/40. 2.1/2 x 2 x 24' pump.
13. Describe proposed or complete of starting any proposed work; of-recompletion. 12/10/2012 Perforated 9025-9141' 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out. 2/7/2013 Perforated 8223-8325.5', 2/8/2013 Acidize w/ 1950 gals 15' 2/12/2013 Release RBP. RIH w/ Spud Date: 11/5/2012 I hereby certify that the information about	d operations. (Clearly state all pertinent details, a). SEE RULE 1103. For Multiple Completions: A , 40 holes. 1, 40 holes. 1	Attach wellbore diagram of proposed completion 7.9 bbls 20# Borate, 112,341# Whitesand holes. Frac w/ 40.4 bbls 15% HCL Acid, 0, 37,193# SLC 20/40. 2 1/2 x 2 x 24' pump. 11/24/2012 dge and belief. DATE 2.19.13
13. Describe proposed or complete of starting any proposed work of recompletion. 12/10/2012 Perforated 9025-9141' 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out. 2/7/2013 Perforated 8223-8325.5', 2/8/2013 Acidize w/ 1950 gals 15' 2/12/2013 Release RBP. RIH w/ Spud Date: 11/5/2012	doperations. (Clearly state all pertinent details, a). SEE RULE 1103. For Multiple Completions: A 1, 40 holes. 1, 40 hole	Attach wellbore diagram of proposed completion 2.9 bbls 20# Borate, 112,341# Whitesand holes. Frac w/ 40.4 bbls 15% HCL Acid, 0, 37,193# SLC 20/40. 2. 1/2 x 2 x 24' pump. 2. 1/24/2012 dge and belief. DATE PHONE: (575)748-1288
13. Describe proposed or complete of starting any proposed work of-recompletion. 12/10/2012 Perforated 9025-9141' 12/11/2012 Acidized w/ 2250 gals 1/3/2013 Frac w/ 189.8 bbls 15% 20/40, 30,969# SLC 20/40. Plug 484 bbls 20# Linear Gel, 3349.5 b 1/7/2013 Plug drilled out. 2/7/2013 Perforated 8223-8325.5', 2/8/2013 Acidize w/ 1950 gals 15' 2/12/2013 Release RBP. RIH w/ Spud Date: 11/5/2012 Thereby certify that the information about the start of the start	d operations. (Clearly state all pertinent details, a). SEE RULE 1103. For Multiple Completions: A , 40 holes. 1, 40 holes. 2, 40 holes. 3, 40 holes. 4, 40 holes. 4	Attach wellbore diagram of proposed completion 2.9 bbls 20# Borate, 112,341# Whitesand holes. Frac w/ 40.4 bbls 15% HCL Acid, 0, 37,193# SLC 20/40. 2.1/2 x 2 x 24' pump. 2.1/24/2012 DATE DATE C.575)748-1288