

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-06854
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name EUNICE KING
8. Well Number 17
9. OGRID Number 4323
10. Pool name or Wildcat PADDOCK
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
CHEVRON U.S.A. INC.

3. Address of Operator
15 SMITH ROAD, MIDLAND TEXAS 79705

4. Well Location

Unit Letter C : 660 feet from the NORTH line and 2310 feet from the WEST line
Section 28 Township 21S Range 37E NMPM County LEA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: SONIC HAMMER, ACIDIZE & CLEAN OUT ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

CHEVRON U.S.A. INC. INTENDS TO SONIC HAMMER, ACIDIZE & CLEAN OUT THE PERFS IN THE SUBJECT WELL.

THE INTENDED PROCEDURE, WELLBORE DIAGRAM & C-144 CLEEZ ARE ATTACHED FOR YOUR APPROVAL.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Scott Haynes TITLE PERMIT SPECIALIST DATE 3/5/2013

Type or print name SCOTT HAYNES E-mail address: TOXO@CHEVRON.COM PHONE: 432-687-7198

For State Use Only

APPROVED BY: Mary S Brown TITLE Compliance Officer DATE 3/8/2013

Conditions of Approval (if any):

MAR 13 2013

Figure 1 is a vertical bar chart illustrating the distribution of 1000 measurements across five stages. The y-axis represents values from 5,000 to 5,350. The legend indicates: Perfs (thin line), Stage 1 (thick line), Stage 2 (dotted line), Stage 3 (thick line), Stage 4 (thin line), and Stage 5 (thick line). The chart shows that Stage 1 has the highest values (around 5,045), while Stage 5 has the lowest values (around 5,330).

284

Contacts: