

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 300 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised August 1, 2011

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-30868
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name WEST PEARL QUEEN UNIT
8. Well Number # 180
9. OGRID Number 25482
10. Pool name or Wildcat PEARL QUEEN
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
STATE OF NEW MEXICO formerly XERIC O&G

3. Address of Operator
1625 N. FRENCH DRIVE HOBBS, NM 88240

4. Well Location
 Unit Letter **K** : **2630** feet from the **SOUTH** line and **2630** feet from the **WEST** line
 Section **28** Township **19S** Range **35E** NMPM County **LEA**

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED PLUGGING PROCEDURE

Spud Date: Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mahey S Brown TITLE Compliance Officer DATE 2/21/2013

or print name _____ E-mail address: _____ PHONE: _____
 : State Use Only

APPROVED BY: Mahey S Brown TITLE Compliance Officer DATE 02-22-2013

Conditions of Approval (if any):

State of New Mexico formerly XERIC OIL & GAS

LEASE NAME WEST PEARL QUEEN UNIT #180 API 30-0 25 - 30868

Section 28 -T 19 S-R 35 E FROM 2630 # / S L, 2630 # / W L.

SPECIAL NOTE—Mud Laden Fluid will consist of 9.5# brine with 12.5# Salt Gel per BBL (25 sacks of gel/ per 100 BBLS Brine). All cement plugs will be 25 sacks of cement or 100', whichever is greater. **Unless otherwise specified in the approved procedure**, cement plugs shall consist of class "C" for depths to 7500'. Class "H" will be used for plugs deeper than 7500'.


1. MIRU plugging unit. Lay down production equipment.
2. Set CIBP @ 4650'. Circulate MLF. Spot 25 sxs cmt on CIBP.
3. ~~Perf/~~ Spot 25 sxs cmt @ 3380'. If perf, WOC and TAG.
4. ~~Perf/~~ Spot 25 sxs cmt @ 1730'. If perf, WOC and TAG.
5. ~~Perf/Spot @~~ 465'. ~~Seq~~ w/ sufficient volume to circ cmt to surface inside/~~outside of csg~~ strings.
6. Cutoff wellhead and anchors, install marker.

-----SPECIAL NOTES-----

PLUGGING & ABANDONMENT WORKSHEET

OPERATOR STATE OF NM - XERIC
 LEASENAME WEST PEARL QUEEN UNIT
 WELL # 180

SECT _____ TWN _____ RNG _____
 FROM _____ N/S L _____ E/W L _____
 TD: _____ FORMATION @ TD _____
 PBTD: _____ FORMATION @ PBTD _____



	SIZE	SET @	TOC	TOC DETERMINED BY	
SURFACE					
INTMED 1					
INTMED 2					
PROD					
	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1					
LINER 2					
	CUT & PULL @			TOP - BOTTOM	
INTMED 1				PERFS	-
INTMED 2				OPENHOLE	-
PROD					

* REQUIRED PLUGS DISTRICT I

RUSTLER (ANEYD)		*
YATES		
QUEEN	4600	
GRAYBURG		
SAN ANDRES		
CAPTAN REEF		*
DELAWARE		
BELL CANYON		
CHERRY CANYON		
BELSHY CANYON		
BONE SPRING		
GLORIETA		*
BLINEBY		
TOBS		
DRINKARD		
ABO		
WC		
PERM		
STRAWN		
ATOCA		
LAGROW		
SAGE		
DEVONIAN		

PLUG	TYPE PLUG	SACKS CMNT	DEPTH
EXAMPLES			
PLUG #1	OH	25 SXS	9850'
PLUG #2	SHOE	50 SXS	8700'-8800'
PLUG #3	CIBP/35'		5300'
PLUG #3	CIBP	25 SXS	5300'
PLUG #4	STUB	50 SXS	4600'-4700'
PLUG #6	REINR SOZ	200 SXS	400'
PLUG #7	SURF	10 SXS	0-10'
PLUG #1			
PLUG #2			
PLUG #3			
PLUG #4			
PLUG #5			
PLUG #6			
PLUG #7			
PLUG #8			
PLUG #9			
PLUG #10			
PLUG #			
PLUG #			

PBTD 5035
 TD 5075