	Submit I Copy To Appropriate District State of New Mexico	Form C-103			
	District I – (575) 393-6161 Energy, Minerals and Natural Resource	Revised August 1, 2011			
	Distance II (575) 749 1000	20.005.00200			
	$\frac{District III}{District III} = (505) 334-6178$ $APR I 0 1220 South St. Francis Dr.$	5. Indicate Type of Lease			
	1000 Rio Brazos Rd., Aztec, NM 87410				
	1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.			
	SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name			
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	A Rock Queen Unit			
	PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Injection	8. Well Number 12			
	2. Name of Operator Celero Energy II, LP	9. OGRID Number			
	Celero Energy II, LP				
	3. Address of Operator ₄₀₀ W. Illinois, Ste. 1601 Midland, TX 79701	10. Pool name or Wildcat Caprock; Queen			
	4. Well Location				
		nd <u>1980</u> feet from the <u>E</u> line			
	Section 23 Township 13S Range 31E	NMPM County Chaves			
	11. Elevation (Show whether DR, RKB, RT, C	ik, etc.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
	NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB P				
	 OTHER: OTHER: I3. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. I. RU wireline and set a CIBP at 2800'. RIH w/tubing and spot 25 sx. Pick up tubing, WOC a minimum of 4 hours and tag. Circulate mud to 2300' and POOH. 2. RU wireline and perf(4) at 2300' and (4) at 1463'. RIH w/tbg & pkr and squeeze 30 sx into 2300'. POOH, RBIH w/BP & PS and tag TOC at/above 2200'. Circulate mud to 1450'. WOC §TAGE 3. RBIH w/packer and squeeze 30 sx into 1463'. POOH w/tbg & pkr, RBIH w/BP & PS and tag TOC at/above 1363'. Circulate mud to 400'. SQZ. LEAKS 4-03' - IZ87' W/100 SXS CMT. WOC § TAGE 4. RU wireline and perf(4) at 363'. RIH w/packer to 350' and establish circulation on 4-1/2"-by-7-5/8" annulus. POOH w/pkr, RBIH w/O-E tubing to 413' and fill the 4-1/2" and 4-1/2"-by-7-5/8" annulus to surface with minimum 100 sx. 5. RD and set P&A marker. Clean and reclaim location. 				
PERFO					
1463					
All cement plugs are Class C w/2% CaCl2. Minimum 9.5 ppg salt mud between all plugs.					
				Spud Date: Rig Release Date:	
		4			
	I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
	SIGNATURE Kia Hunt TITLE Regulatory Analysi	DATE <u>04/10/2013</u>			
	Type or print name Lisa Hunt E-mail address: lhunt@ce	leroenergy.com PHONE: (432)686-1883			
	For State Use Only A 1 2: L				
	APPROVED BY: August Diown Stitle Complian	<u>nelificer date 4-/17/2013</u>			
	7. ·				
		APR 17 2013			

,



