r ·	Form 3160-5 (August 2007)	De	UNITED STATES EPARTMENT OF THE INTERIOR HOBBS OCD			FORM APPROVED OMB NO. 1004-0135			
		BU	JREAU OF LAND MANAG			Expires: July 31, 2010 5. Lease Serial No. NMNM05519			
	SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter aMAY abandoned well. Use form 3160-3 (APD) for such proposals.					8 2013	6. If Indian, Allottee or Tribe Name		
	SUBMIT IN TRIPLICATE - Other instructions on reverse side. RECEIVED						7. If Unit or CA/Agreen	7. If Unit or CA/Agreement, Name and/or No.	
	1. Type of Well ☐ Oil Well ☐ Gas Well ☑ Other: INJECT/ON					8. Well Name and No. MRU 263			
	2. Name of Operator Contact: TERRY B CALLAHAN LINN OPERATING INCORPORATED E-Mail: tcallahan@linnenergy.com						9. API Well No. 30-025-21857-00	9. API Well No. 30-025-21857-00-S1	
	3a. Address3b. Phone No. (include area code)600 TRAVIS STREET SUITE 5100Ph: 281-840-4272HOUSTON, TX 77002/					le)	10. Field and Pool, or Exploratory PEARL		
	4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						11. County or Parish, and State		
	Sec 26 T19S R34E SWSE 330FSL 1980FEL / 32.625013 N Lat, 103.528913 W Lon						LEA COUNTY, N	M	
	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
	TYPE OF S	TYPE OF SUBMISSION TYPE					1		
	□ Notice of	Intent	☐ Acidize ☐ Alter Casing	- •	Deepen Fracture Treat		Production (Start/Resume) Water Shut-Off Reclamation Well Integrity		
	🛛 Subseque	nt Report	Casing Repair	New Construction		Reco	mplete	□ Other	
	🗖 Final Aba	ndonment Notice	Change Plans Convert to Injection	=	-		oorarily Abandon r Disposal		
	following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed and the operatorhas. Mail CLAWATON 4/3/2013 ? MOVING PLUGGING EQUIPMENT TO LOCATION. 4/4/2013 - ND WH NU BOP. LD 140 JTS 2 3/8 IPC. TBG. RIH W/ 142 JTS 2 3/8 WS TO 4580'. CIRC HOLE W/ 80 BBLS WATER. MIX 15 SKS CMT PLUG. HYRRAULIC HOSE BUSTED. PUMP CMT ON GROUND. SISD. 4/5/2013 - REPAIR BAD HYDRAULIC HOSE. SPOT 25 SKS CLASS C CMT @ 4580'-4330' POH W/ 15 STANDS TBG. WOC, 4 HRS. RIH W/ TBG TAG PLUG @ 4323' CIRC HOLE W/80 BBLS. MUD LADEN FLUID. POH W/ 52 STANDS 2 3/8 WS. RIH W/ 5 1/2" PKR.& 52 STANDS 2 3/8 WS. POH LAYING DWN 43 JTS. 2 3/8 WS. SISD. 4/8/2013 - RU WL & PERFORATE 4 SHOTS @ 3650' PERF 5 1/2" CSG. POH W/ WL. SET PKR @ 3238' RU PUMP TRK.PRESSURED UP CSG TO 1700 PSI. HELD PRESSURE. POH W/ 2 3/8 WS & PKR. RIH OPEN ENDED TO 3705'.SPOT 30 SKS CLASS C CMT FROM 3705'- 3460'. OKAYED BY MARLAND W/ BLM. POH W/ 30 JTS. 2 3/8								
	14. I hereby certify that the foregoing is true and correct. Electronic Submission #204878 verified For LINN OPERATING INCOR Committed to AFMSS for processing by JOHN Name (Printed/Typed) TERRY B CALLAHAN				PORATED, sent to the Hobbs				
	Signature (Electronic Submission)				Accepted as to plugging of the well bore. Liability under bond is retained until				
	THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
	APProved By ACCEPTED				JAMES A		'S	Date 05/06/2013	
	Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				Office Hobbs	5			
	Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or presentations as to any national transformation.								
	<u>- Mark - 12</u>		ISED ** BLM REVISED	•				** / //	

Additional data for EC transaction #204878 that would not fit on the form

32. Additional remarks, continued

WS. SISD.

4

4/9/2013 - RIH W/ 2 3/8 WS TO 3384' TAG CMT PLUG. POH W/ 98 JTS 2 3/8 TBG. LAYING DWN 21 JTS. RU WL PERF @ 3326' W/ 4 SHOTS. POH WL. RIH W/ 5 1/2" PKR. TO 3051'. PRESSURE CSG TO 1500 PSI HELD FOR 10 MINS. RLSE PKR POH W/ 2 3/8 WS & PKR. CALL BLM PAUL FLOWERS HE OK'D SPOTTING 30 SKS PLUG @ 3384-3276'.

4/10/2013 - RIH open ended to 3363' & spotted 25 sx Class "C" cmt. from 3363 - 3276'. POH w/20 stds. WOC. Opened well, RIH w/tbg. Tagged plug @ 3118'. POH std. back 30 stds. LD 40 jts. RU WL. RIH & perf. 1992'. POH RD WL. RIH w/27 stds. to 1681'. Set pkr., est. inj. rate of 1 BPM @ 1400 PSI. Squeezed 45 sx Class "C" cmt. SI well w/700 PSI.

4/11/2013 - RU WL RIH and tagged plug @ 1871'. POH LD 54 jts. and 5 1/2" pkr. RU WL & perf shot. RIH to 238' and perforated csg. POH RD WL. RIH w/ 5 1/2" pkr. & 1 jt. Set pkr. Established 1 1/2 BPM inj. rate @ 250 PSI, circulating to surface. Unset pkr. ND BOP. RIH w/5 1/2" pkr. on 6' sub. Set pkr. Squeezed 100 sx Class "C" cmt. to surface @ 100 PSI. Dug out cellar. Ready to cut off wellhead. Unset pkr. Cmt. @ 20'. Filled to surface w/15 sx cmt.

4/12/2013 - Cut off wellhead, Installed ground level marker. Backfilled cellar. RDPU and equipment.

(PLEASE ATTACHMENT)