Submit 1 Copy To Appropriate District Office Submit 1 Copy To Appropriate District Office	Form C-103
District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 APR 17 2013 OIL CONSERVATION DIVISION	30-025-24869
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	29810 NMLC-0065710-A
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR: USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Lusk West Delaware Unit
1. Type of Well: Oil Well Gas Well Other SWD-Injector	8. Well Number 007
Name of Operator Cimarex Energy Co. of Colorado	9. OGRID Number 162683
3. Address of Operator	10. Pool name or Wildcat
600 N. Marienfeld Street, Suite 600, Midland, TX 79701	Lusk; Delaware, West
4. Well Location	
	2300 feet from the East line
Section 20 Township 19S Range 11. Elevation (Show whether DR, RKB, RT, GR,	32E NMPM Lea County
11. Elevation (Show whether DR, RRB, RT, GR, 3581' GR	eic.)
12. Check Appropriate Box to Indicate Nature of Noti	ce, Report or Other Data
NOTICE OF INTENTION TO:	UBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W	
	DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CENDOWNHOLE COMMINGLE	MENT JOB []
SOTTITIOEE COMMITTIOEE	
OTHER: MIT	
13. Describe proposed or completed operations. (Clearly state all pertinent details	s, and give pertinent dates, including estimated date
	s, and give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure 	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure 	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure 	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure 	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure 	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure 	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure 	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure 	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure 	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure Held okay. 	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure Held okay. Spud Date: Rig Release Date:	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of ed up to 320# on casing and held for 33 minutes.
 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure Held okay. 	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of ed up to 320# on casing and held for 33 minutes.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure Held okay. Spud Date: Rig Release Date:	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of ed up to 320# on casing and held for 33 minutes.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure Held okay. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my know SIGNATURE	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of ed up to 320# on casing and held for 33 minutes. Idedge and belief. Completions
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure Held okay. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my known SIGNATURE Michelle Chappell E-mail address:mchappell@cima	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of ed up to 320# on casing and held for 33 minutes.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure Held okay. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my know SIGNATURE	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of ed up to 320# on casing and held for 33 minutes. Idedge and belief. Completions
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 03/22/13 Notified OCD of test. Preformed bradenhead test and pressure test. Pressure Held okay. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my known SIGNATURE Michelle Chappell E-mail address:mchappell@cima	s, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of ed up to 320# on casing and held for 33 minutes. Idedge and belief. Completions

