Submit I Copy To Appropriate District	State of New Mexico	Form C-103
Office District 1	Energy, Minerals and Natural Reson	urces October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-025-04060
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISI	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	ALS TO DRILL OR TO DEEPEN OR PLUG BACK T	i I
PROPOSALS.)	ATION FOR PERMIT" (FORM C-101) FOR SUCH	North Monument G/SA Unit Blk. 9
1. Type of Well: Oil Well	Gas Well Other Injection well.	8. Well Number 7
2. Name of Operator	•	9. OGRID Number 873
Apache Corp.		10. Pool name or Wildcat
3. Address of Operator P O box Drawer D Monument NM 8	38265	Eunice Monument G/SA
4. Well Location	10203	Edition (Monament G/S/1
	1080 feet from the N	line and1980feet from the
E line	1980leet Holli thei\	The and1980leet from the
Section 25	Township 19S Range	36E NMPM Lea County
Section 23	11. Elevation (Show whether DR, RKB, R7	
	11. Elevation (Show whether DK, KKB, KI	, GN, cic.)
Exceller (g) to experience and episitivities resonance expeller than the experience is severe order a metro as a colonial.		Principles and a second
12. Check A	ppropriate Box to Indicate Nature of	Notice, Report or Other Data
		•
NOTICE OF INT		SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		NAL WORK ALTERING CASING
TEMPORARILY ABANDON  PULL OR ALTER CASING	— I	ENCE DRILLING OPNS.□ P AND A □  G/CEMENT JOB □
DOWNHOLE COMMINGLE	MOETIFEE COMITE GOOD	DICEMENT 30D
Botti iore ooimmitoee		
OTHER:	OTHER	: FAILED BHT
13. Describe proposed or comple	eted operations. (Clearly state all pertinent of	details, and give pertinent dates, including estimated date
		ultiple Completions: Attach wellbore diagram of
proposed completion or reco	mpletion.	
Move in Gandy truck and pressure the	e casing and chart for 32 minutes. Starting p	ressure 540 # and finale pressure 540 #
Wove in Gundy track and pressure the	o dasing and chart for 32 minutes. Starting p	resoure 5 to 11 and think pressure 5 to 11
Spud Date:	Rig Release Date:	
Spud Bate.	Kig Keleuse Date.	
,	•	
Lhereby certify that the information a	bove is true and complete to the best of my	knowledge and belief
	oove is true and complete to the best of my	knowledge and belief.
()		~ K 12
SIGNATURE	TITLE Instrument	TechDATEDATE
Type or print name Jim Ellison		
· · · ——	E mail address. ID El	lican@anachacaarn aam BHONE.
For State Use Univ	E-mail address: _JD.El	lison@apacheccorp.com_ PHONE:
For State Use Only		
APPROVED BY	E-mail address: _JD.El	lison@apacheccorp.com_PHONE:  DAJE 13-2013
5/1		

