

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

HOBBS OCS

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 10 2013

WELL API NO. 30-025-37521 ✓
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Cotton Draw Unit ✓
8. Well Number 92 ✓
9. OGRID Number 16696
10. Pool name or Wildcat
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3450'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other TA Well

2. Name of Operator
OXY USA Inc. ✓

3. Address of Operator
P.O. Box 50250 Midland, TX 79710

4. Well Location
Unit Letter A : 100 feet from the north line and 700 feet from the east line
Section 16 Township 25S Range 32E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3450'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

TD-4940' PBTD-600' CIBP-600'

8-5/8" 24# csg @ 635' w/ 450sx, 12-1/4" hole, TOC-Surf-Circ

DRILL OUT CIBP - RHTO 4250' - CIRCM LF

1. RIH & tag CIBP @ 600', M&P 40sx cmt to 500'

2. M&P 95sx cmt @ 250' to surface SPOT 35sx cmt @ 1800' - WOC/TA9

10# MLF between plugs

3. SPOT 45'sx cmt @ 690'. (85/8 shoe & T/S) - WOC/TA9

4. CIRCM cmt - FROM 250' TO SURFACE

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Regulatory Advisor DATE 6/7/13

Type or print name David Stewart E-mail address: david_stewart@oxy.com PHONE: 432-685-5717

For State Use Only

APPROVED BY [Signature] TITLE Dist. Mgr DATE 6-12-2013

Conditions of Approval (if any):


Oil Conservation Division - Hobbs office: **Must be Notified 24 hours prior to the beginning of Plugging Operations begin.**

JUN 12 2013

OXY USA Inc. - Current
Cotton Draw Unit #92
API No. 30-025-37521

1/06-CIBP @ 600'

300sx cmt @ 4940-4272' Tagged



12-1/4" hole @ 635'
8-5/8" csg @ 635'
w/ 450sx-TOC-Surf-Circ

TD-4940'

OXY USA Inc. - Proposed
Cotton Draw Unit #92
API No. 30-025-37521

95sx @ 250'-Surface

40sx @ 600-500'
1/06-CIBP @ 600'


Circumferential
From 250' $\nearrow$
To Surface

@ 690' $\nearrow$
Spot 455x Out
WDC-TA7

Plug @ 1800'

300sx cmt @ 4940-4272' Tagged

12-1/4" hole @ 635'
8-5/8" csg @ 635'
w/ 450sx-TOC-Surf-Circ



TD-4940'