

Submit 1 Copy To Appropriate District  
Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-23427	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name East Pearl Queen Unit	
8. Well Number 59	
9. OGRID Number	
10. Pool name or Wildcat Pearl Queen	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator State of New Mexico formerly Xeric Oil & Gas Corp	
3. Address of Operator 1625 N. French Drive Hobbs, New Mexico 88240	
4. Well Location Unit Letter <u>H</u> : 2735 feet from the <u>South</u> line and <u>1300</u> feet from the <u>East</u> line Section <u>27</u> Township <u>19S</u> Range <u>35E</u> NMPM County <u>Lea</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			

SEE ATTACHMENTS: PROCEDURE & SCHEMATIC

Spud Date:  Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Whitaker TITLE Compliance Officer DATE 05/07/2013

Type or print name Mark Whitaker E-mail address:  PHONE: 575-393-6161  
For State Use Only

APPROVED BY: [Signature] TITLE Dist MGR DATE 5-7-2013  
Conditions of Approval (if any):

(2)

JUN 18 2013

OPERATOR St. of NM formerly Xeric Oil & Gas  
LEASENAME East Pearl Queen Unit

OPERATOR St. of NM formerly Xeric Oil & Gas  
LEASENAME East Pearl Queen Unit

SECT 27 TWN 19S RNG 35E  
FROM 2735 (S) 1300 (E) W L  
TD: 4882 FORMATION @ TD  
PBTD: 4501 FORMATION @ PBTD

85/8  
@ 405  
TOC CIRC

	SIZE	SET @	TOC	TOC DETERMINED BY	
SURFACE	8 5/8	405	SURF.	CIRC.	
INTMED 1					
INTMED 2					
PROD	5 1/2	4882'	?	650 SX pump	
	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1					
LINER 2					
	CUT & PULL @			TOP - BOTTOM	
INTMED 1			PERFS	4701 - 4870	
INTMED 2			OPENHOLE	-	
PROD					

RUSTLER (AKNEYD)	1750'
WATER B. SALT	3400
QUEEN	
GRAYBURG	
SAN ANDRES	
CAPTAIN REEF	
DELAWARE	
BELL CANYON	
CHEERY CANYON	
BRUEY CANYON	
BONE SPRING	
OLORIETA	
BLINDEERY	
TUES	
ORINGARD	
ABO	
KAC	
PERN	
STRAWN	
ATOKA	
MOCKLOW	
MISS	
DEVORIAN	

[illegible]

PBTD  $\pm 450'$

Perfs 4701' - 4870'

5 1/2  
@ 4882  
TOC UNKNOWN  
(650 SX cmt)

1972 - pumped 75 sx  
cmt down csg.  
Displaced to 4501.

TD 4882

State of New Mexico formerly Xeric Oil & Gas Corp  
East Pearl Queen Unit No. 59

Go in hole and tag PBTD at 4501'. Cap w/ 25 sx. Pressure test csg.  
Circulate hole w/ 9.5 ppg brine w/ 25 sx salt gel per 100 bbls.  
Spot 25 sx cmt at 3400'.  
Perf at 1750'. Attempt to sqz w/ 25 sx cmt. WOC and Tag.  
Perf at 455'. Circulate cmt to surface.  
Cut off wellhead and install dry hole marker.