

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised August 1, 2011

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-28954
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> <i>Fed</i>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit Section 30
8. Well Number 332
9. OGRID Number: 157984
10. Pool name or Wildcat Hobbs (G/SA)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3662 KB

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other *Inject*

2. Name of Operator
Occidental Permian Ltd.

3. Address of Operator
HCR 1 Box 90 Denver City, TX 79323

4. Well Location
 Unit Letter J : 2457 feet from the South line and 1598 feet from the East line
 Section 30 Township 18S Range 38E NMPM Lea County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK PLUG AND ABANDON
 TEMPORARILY ABANDON CHANGE PLANS
 PULL OR ALTER CASING MULTIPLE COMPL
 DOWNHOLE COMMINGLE

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPERATIONS PLUG AND ABANDON
 CASING/CEMENT JOB

Per Underground Injection Control Program Manual
11.6 C Packer shall be set within or less than 100 feet of the uppermost injection perfs or open hole.

OTHER:
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- Clean out well to 4323'
- Set CIBP @4246' & CICR @4238'
- Pressure test, POH w/ pkr and workstring
- Perforate 4214-21', 4225-40'
- RIH w/ treating pkr and set @4176'
- Acid treat perforations with 1100 gals of 15% NEFE Acid
- RIH w/ injection equipment, return to injection

HOBBS OCD

JUN 21 2013

RECEIVED

The Oil Conservation Division
MUST BE NOTIFIED 24 Hours

Condition of Approval: notify
OCD Hobbs office 24 hours

Spud Date: **Prior to the beginning of operations**

Rig Release Date: **prior of running MIT Test & Chart**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Rubbie Underhill* TITLE well analyst DATE 5-23-13

Type or print name Rubbie Underhill E-mail address: Robert.Underhill@oem.nm.gov PHONE: 806-592-6287

APPROVED BY: *[Signature]* TITLE Dist Mgr DATE 6-24-2013

JUN 25 2013