

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-2004

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505
505-833-0000

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

1301 W. Grand Ave, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd, Aztec, NM 87410

JUL 01 2013

SUNDRY NOTICES AND REPORTS ON WELLS		RECEIVED	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)		WELL API NO. 30-025-29085	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐	
2. Name of Operator Occidental Permian Ltd.		6. State Oil & Gas Lease No.	
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323		7. Lease Name or Unit Agreement Name South Hobbs (G/SA) Unit	
4. Well Location Unit Letter J : 1685 Feet From The South Line and 2475 Feet From The East Line Section 5 Township 19-S Range 38-E NMPM Lea County		8. Well No. 189	
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3614' GL		9. OGRID No. 157984	
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth of Ground Water _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		10. Pool name or Wildcat Hobbs (G/SA)	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG & ABANDONMENT ☐
PULL OR ALTER CASING ☐	Multiple Completion ☐	CASING TEST AND CEMENT JOB ☐	
OTHER: _____	☐	OTHER: _____	☐

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RUPU & RU.
2. NU BOP/ND wellhead.
3. RU wire line and shoot drain holes @3870'. RD wire line.
4. POOH and lay down ESP equipment.
5. RIH w/bit & tag @4208'. POOH w/bit.
6. RIH w/ESP equipment on 128 jts of 2-3/8" tubing. Intake set @4046'
7. ND BOP/NU wellhead.
8. RDPU & RU. Clean location and return well to production.

RUPU 04/19/2013
RDPU 04/24/2013

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Mendy A. Johnson TITLE Administrative Associate DATE 06/27/2013
TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy.johnson@oxy.com TELEPHONE NO. 806-592-6280


For State Use Only

APPROVED BY [Signature] TITLE DISTRICT DATE 7-3-2013
CONDITIONS OF APPROVAL IF ANY:

JUL 08 2013

June 20, 2013

Work Plan Report for Well:SHOU-189J05



Survey Viewer