State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004


FILE IN TRIPLICATE	OIL,CONS	SERVATION DIVISION	
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	Sa	O South St. Francis Dr. anta Fe, NM 87505	WELL API NO. 30-025-07491
<u>DISTRICT II</u>	JUL 1 5 2013		5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210	JOT I 2 5010		STATE FEE X
DISTRICT III			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	<u>neceived</u>		
SUNDRY NO	TICES AND REPORTS	ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)		North Hobbs (G/SA) Unit	
	PPLICATION FOR PERMIT"	(Form C-101) for such proposals.)	Section 31 8. Well No. 311
Type of Well: Oil Well X	Gas Well O	ther	311
Name of Operator Occidental Permian Ltd.			9. OGRID No. 157984
3. Address of Operator			10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 4. Well Location	79323		/
Unit Letter B : 440	Feet From The North	Line and 2310 Fee	et From The <u>East</u> Line
Section 31		8-S Range 38-E	E NMPM Lea County
	11. Elevation (Show wheth 3649' GR	er DF, RKB, RT GR, etc.)	
Pit or Below-grade Tank Application or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS [COMMENCE DRILLING OP	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	IT JOB
OTHER:		OTHER: Casing leak r	repair
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. RUPU & RU. ND wellhead/NU BOP. RU wire line & shot drain holes @3755'. RD wire line. POOH & lay down ESP equipment. RIH w/RBP set @3939'. Tested casing to 600 and leaked. RIH w/packer set in casing to isolate leak. RIH w/2nd RBP set @548'. Dump 3 sacks cement on top of RBP. Found casing not sealing with tubing head packoff. Pulled casing up and cut off 2-3/4". Installed new tubing head. Tested to 1500 PSI and tested OK. POOH w/RBP @548. Ran caliper log to verify casing size. Found leak 16 foot from surface on collar. RIH w/RBP set @550'. Dump 3 sacks of sand on RBP. Cut 7" casing @4' from surface, POOH & lay down. RIH w/2 jts of 7" casing and screwed back into casing. ****see attached sheet for additional data**** 			
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be			
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved			
closed according to NMOCD guidelines		or an (attached) alternative	
closed according to NMOCD guidelines SIGNATURE		or an (attached) alternative plan	e OCD-approved
Mard	, a general permit	or an (attached) alternative plan TITLE Administrative	Associate DATE 07/11/2013
SIGNATURE MINDLY	, a general permit	or an (attached) alternative plan TITLE Administrative	Associate DATE 07/11/2013
SIGNATURE Mendy A. Jo	, a general permit	or an (attached) alternative plan TITLE Administrative	Associate DATE 07/11/2013
SIGNATURE Mendy A. Jo For State Use Only	, a general permit	or an (attached) alternative plan TITLE Administrative and iohnson@oxy.com	Associate DATE 07/11/2013

NHU 31-311 API 30-025-07491

- 10. RIH w/packer and tested casing to 600 PSI. Tested OK. POOH w/packer.
 11. Wash sand of f and POOH w/ both RBPs and lay down.
 12. RIH w/ESP equipment on 124 jts of 2-7/8" tubing. Intake set @3797'.
- 13. ND BOP/NU wellhead.
- 14. RDPU & RU. Clean location and return well to production.

RUPU 03/01/2013 RDPU 03/13/2013

Work Plan Report for Well: NHSAU 311-31



Survey Viewer