Submit 3 Copies To Appropriate District Office	State of New Me	exico	Form C-103	
District 1			WELL API NO.	
1625 N. French Dr., Hobbs, NM 87240 District II ON DIVISION			30-025-11415	
District II 1301 W. Grand Ave., Artesia, NM 88210 JULE PLZCONSERVATION DIVISION District III 1220 South St. Francis Dr.			5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505			STATE 🔯 / FEE 🗌	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No. 24695	
	ES AND REPORTS ON WEL		7. Lease Name	or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC, PROPOSALS.)			Stuart Langl	ie Mattix Unit
1. Type of Well: Oil Well Gas Well Other Water injection			8. Well Number	
2. Name of Operator			9. OGRID Number	
Energen Resources Corporation			162928	
3. Address of Operator			10. Pool name or Wildcat	
3300 N. "A" St., Bldg 4, Ste. 100, Midland, TX 79705 Langlie Mattix 7 RVRS Queen Grayburg 4. Well Location				
	1000 for form the Nor	±1. 1. 1	660 6 46	Wort I'm
Unit Letter E:	1980 feet from the Nor	line and	660 feet f	rom the West line
Section 2		Range 37E	NMPM Lea	County New Mexico
	11. Elevation (Show whether .	DR, RKB, RT, GR, etc '6' GR	c.)	
12 Charle A	·			·Du
12. Check Ap	opropriate Box to Indicate 1	Nature of Notice, I	Report, or Othe	er Data
NOTICE OF INTENTION TO: SUBS			SEQUENT REPORT OF:	
_			OLGOLIVI IV	
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK				ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI	_	P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JO	OB	
DOWNHOLE COMMINGLE				
OTHER.		OTHER.		
OTHER:		OTHER:		
13. Describe proposed or completed of starting any proposed work). or recompletion.				
See attached procedure				
•				
				obbs office Must Be Notified ugging Operations
			H	obbs office Music
			ATION DIVISION - TI	ugging Ope
	•	OIL CONSERV	to the beginning	
		24 hours pri	ATION DIVISION - H to the beginning of Pl	
6 10	n' n 1			
Spud Date:	Rig Relea	se Date:		
I hereby certify that the information at	bove is true and complete to the	best of my knowledge	and belief.	
		-		
SIGNATURE A SO	TITI		y Analyst	DATE 7/9/13
Type or print name <u>Jenifer Sorley</u>	E-ma	jenifer.sorley@e ail address:	mergen.com	PHONE <u>432-818-1732</u>
For State Use Only				b
APPROVED BY Juny	ale TIT	LDIST ME		DATE -18-2013
Conditions of Approval (if any).	***		.,	JUL 1 8 2013
				JUL TO TOIS

SLMU #102

Stuart Langlie Mattix Unit Lea County, NM

1980' FNL and 660' FWL Sec 2, T25S, R37E API - 30-025-11415 Completion Date: 6/1/1938

Plug & Abandon Procedure

3 RIH and tag CIBP @ 3,190'. Spot 35 sxs cement on CIBP. WOC & tag.

Perfeso 355xcmtel: 5 Perforate at 1,125' and squeeze with 25 sxs cement, WOC & tag.

6 Perforate at 315'. Squeeze and circulate cement to surface.

7 Cut off all casing strings at base of cellar or 3' below restored ground level.

- 8 Cover wellbore with metal plate welded in place or with cement cap.
- **9** Erect capped abandonment marker inscribed with well information.
- 10 Cut off dead man anchors and fill in cellar.

11 Clean and restore location to natural condition and fulfill any and all regulatory

Prepared by: Brian Hillger 7/8/2013



SLMU #102

Stuart Langlie Mattix Unit Lea County, New Mexico 1980' FNL and 660' FWL Sec 2, T25S, R37E

API - 30-025-11415

Spud Date:

1938

KB:

TD:

3464

Completion Date:

6/1/1938

GL:

PBTD:

3404

3170 **Current WBD**

Surface Casing:

8-5/8" 24# K-55 3 csg @ 128'

Cmt w/ 100 Sx to Surface (Circulated)

Intermediate Casing:

8-5/8" 28# csg @ 1,298'

Cmt w/ 100 Sx to 471' (Calculated)

CIBP Set @ 3,190'

Production Casing:

7" 20# csg @ 3,237'

Cmt w/ 250 Sx to 930' (Calculated)

PBDT: 3,404'

TD: 3,464'

B. Hillger

7/8/2013



SLMU #102

Stuart Langlie Mattix Unit Lea County, New Mexico 1980' FNL and 660' FWL Sec 2, T25S, R37E

API — 30-025-11415

Spud Date:

1938

KB:

TD:

3464

Completion Date:

B. Hillger

6/1/1938

GL:

3170

PBTD:

3404

