

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

JUL 18 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>WELL API NO. 30-025-38125</p>
<p>1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/></p>		<p>5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/></p>
<p>2. Name of Operator Occidental Permian Ltd.</p>		<p>6. State Oil & Gas Lease No.</p>
<p>3. Address of Operator 2611 Plains Hwy Denver City, TX 79323</p>		<p>7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit Section 19</p>
<p>4. Well Location Unit Letter <u>B</u> : <u>402</u> feet from the <u>North</u> line and <u>1878</u> feet from the <u>East</u> line Section <u>19</u> Township <u>18S</u> Range <u>38E</u> NMPM Lea County</p>		<p>8. Well Number 638</p>
<p>11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3676' KB</p>		<p>9. OGRID Number: 157984</p>
		<p>10. Pool name or Wildcat Hobbs (G/SA)</p>

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) POOH with prod equip.
- 2) Clean out to 4440'
- 3) Perforate from 4110-11', 4128-31', 4138-55'
- 4) Acid treat with 1220 gal.
- 5) RIH with ESP
- 6) Return well to production

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steve Snead TITLE Lift Specialist DATE 7/11/2013

Type or print name Steve Snead E-mail address: steve_snead@oxy.com PHONE: 806-592-6312
For State Use Only

APPROVED BY: [Signature] TITLE Petroleum Engineer

DATE

JUL 24 2013

Conditions of Approval (if any):

JUL 24 2013