

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

HOBBS OCD
JUL 25 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-104) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-37451
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> INJECTOR		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Occidental Permian Ltd.		6. State Oil & Gas Lease No.
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323		7. Lease Name or Unit Agreement Name North Hobbs G/SA
4. Well Location Unit Letter <u>C</u> : <u>288</u> feet from the <u>North</u> line and <u>1650</u> feet from the <u>West</u> line Section <u>29</u> Township <u>18S</u> Range <u>38E</u> NMPM Lea County		8. Well Number 29-711
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3660' KB		9. OGRID Number: 157984
		10. Pool name or Wildcat Hobbs (G/SA)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: Coiled Tubing Cleanout



SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER:



13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) Rig up Coiling Tubing Unit with Perf Clean Tool
- 2) TIH to 4402'
- 3) Pull up with perf clean tool to 4200'
- 4) Run perf clean tool with water across perforations 4258-4353'
- 5) Close backside and repeat perf wash from 4258-4353' with 2500 gals 15% NEFE HCL
- 6) Pump 10 bbls gel sweep to bring fines to the surface
- 7) POOH with CT and RD Coil Tubing Unit
- 8) Return well to injection

Per Operator

During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal, per OCD Rule 19.15.17.

CONDITION OF APPROVAL: Notify OCD DISTRICT OFFICE 24 HOURS prior to STARTING THE WORKOVER. 3 Rele:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Injection Well Analyst DATE 7-18-13

Type or print name Robbie Underhill E-mail address: Robert_Underhill@oxy.com PHONE: 806-592-6287
For State Use Only

APPROVED BY: [Signature] TITLE DIST MGR DATE 7-29-2013
Conditions of Approval (if any):

JUL 29 2013