Submit 1 Copy To Appropriate District	State of New Mo	vice		Form C-103
Office District I – (575) 393-6161	State of New Mexico Energy, Minerals and Natural Resources		Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	OIL CONSERVATION DIVISION		WELL API NO. 30-025-06639	
811 S. First St., Artesia, NM 88210			5. Indicate Type of Lease	FEDERAL B
District III – (505).334-6178 1000 Rio Brazos Rd., Azteč, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505		STATE FEE	
1220 S. St. Francis Dr., Santa Fe, NM		6. State Oil & Gas Lease No. NMLC032096A / WBDU 120042X		
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			West Blinebry Drinkard Unit (WBDU)	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other WSW			8. Well Number 067	
2. Name of Operator Apache Corporation			9. OGRID Number 873	
3. Address of Operator			10. Pool name or Wildcat	
303 Veterans Airpark Lane, Suite 3000 Midland, TX 79705			WSW; San Andres (96221)	
4. Well Location Unit Letter A : 660 feet from the North line and 660 feet from the East line				
Section 17	Township 21S Ra	inge 37E	NMPM Count	ty Lea
	11. Elevation (Show whether DR, 3500' GL	RKB, RT, GR, etc.	)	
		<u></u>		
12. Check	Appropriate Box to Indicate N	ature of Notice,	Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				
PULL OR ALTER CASING		CASING/CEMEN		
	]			
OTHER: PB w/CIBP				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or r	ecompletion.			
Presently the well is shut-in with equipment out of the hole. We suspect that the lower set of San Andres perforations are responsible for				
the issues with radioactive scaling that this well has been plagued with. WBDU 43WSW; the other WBDU source well is not perforated in this interval, and does not have these issues with radioactive scale.				
		incord the lower on	t of porforations, and run ha	at in with the ESD
Apache's plan is to set a CIBP at 4400' with 30' of cement on top to suspend the lower set of perforations, and run back in with the ESP equipment and internally coated tubing and return the well to production.				
We need to return the well to production as soon as possible, without it, we are not able to inject required volumes of water in our				
waterflood, and our production w	ill begin to suffer as a result.			
	<u> </u>	ſ	]	
Spud Date: 12/31/1949	Rig Release Da	ate:		
I hereby certify that the information	n above is true and complete to the b	est of my knowledg	e and belief.	*************
0 1	1			
SIGNATURE JOSA HA	the TITLE Sr. Sta	aff Reg Tech	DATE7/	30/2013
Type or print name Reesa Hollan	d Fisher E-mail addres	s: Reesa Holland@apa	checorp.com PHONE:	432/818-1062
For State Use Only	$\supset 1 / \neg$	1 -		
APPROVED BY	incher TITLE D	T MAR	– DATE –	30-2013
Conditions of Approval (IPany):	/ /			
			JUL 30	2012
/				6U U



