

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

AUG 15 2013

State of New Mexico
Energy Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised July 18, 2013

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-03842
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator ROCKY SMITH SWD SYSTEMS, INC		6. State Oil & Gas Lease No. B-1553
3. Address of Operator 1515 WAZEE, SUITE 350, DENVER CO. 80202		7. Lease Name or Unit Agreement Name STATE 'E'
4. Well Location Unit Letter F : 1650 feet from the N line and 2310 feet from the W line Section 1 Township 17S Range 36E NMPM County LEA		8. Well Number 17
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 270801
		10. Pool name or Wildcat LOVINGTON-QUEEN

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: CONVERT TO SWD OR P&A ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

PROPOSED TO CONVERT WELL TO SWD. RIH WITH WORKSTRING, TAG CIBP AND CEMENT @ ~ 3750', DRILL OUT PLUG AND SQUEEZE QUEEN PERFS, PRESSURE TEST 7" CSG, DRILL OUT CIBP @ 7838' AND SQUEEZE DRINKARD AND UPPER ABO PERFS. FILE FORM C-103 WITH NMOC. SHOULD THE 7" CSG HAVE SEVERE INTEGRITY PROBLEMS WELL WILL BE P&A'd.

WORK WILL START AS SOON AS CONTRACTOR AVAILABILITY.

SUBMIT C-103 FOR P/A IF PROBLEMS WITH CASING INTEGRITY ARE FOUND.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

DATE

Type or print name

E-mail address:

PHONE:

For State Use Only

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):

AUG 29 2013

F-1-175-36E

API # 30-025-03842

22-141 50 SHEETS
22-142 100 SHEETS
22-144 200 SHEETS




13 3/8 @
263' w/
275 SX
-CIRC-

9 5/8 @
3283' w/
300 SX
TOC @ 1550

7" @ 8494
w/500 SX &
500 FT³ PERLITE
TOC @ 5175'
TEMP SURV

* 2/13/91
LOST TOOLS @ 5399
10/4/2000
CIBP @ 7838
w/3 SX



CONVERT TO SWD

F-1-175-36E

API # 30-025-03842

22-141 50 SHEETS
22-142 100 SHEETS
22-144 200 SHEETS

GAMPA

13 3/8 @
263' w/
275 SX
- CIRC -

9 5/8 @
3283' w/
300 SX
TOC @ 1550

7" @ 8494
w/500 SX &
500 FT³ PERLITE
TOC @ 5175'
TEMP SURV

* 2/13/91
LOST TOOLS @ 5399
10/4/2000
CIBP @ 7838
w/3 SX

TOC @ 3385
CIBP @ 3800' w/50' CEMENT
≡ 3867-3900

PERF 4847
SQ 1000 SX

CIBP @ 7838 w/3 SX
≡ 7910-7980 DRINKARD

≡ 8375-8432 ABO

CONVERT TO SWD

