## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	TION DIVISION		
<u>DISTRICT I</u> 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-07491	
DISTRICT II	<del></del>		5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE 💉
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410	THOUGH AND DEPONTS ON HE	1.0	7. Lease Name or Unit Agreement	Name
SUNDRY NOTICES AND REPORTS ON WELLS			_	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			NORTH HOBBS (G/SA) UNIT Section 31	
1. Type of Well:			8. Well No. 311	
Oil Well X Gas Well Other				
Name of Operator     Occidental Permian Ltd.			9. OGRID No. 157984	
3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200  4. Well Location				
Unit Letter B: 440 Feet From The NORTH 2310 Feet From The EAST Line				
Section 31	Township 18-S	Range 38-E	NMPM	LEA County
	11. Elevation (Show whether DF, RK 3649' GR	B, RT GR, etc.)		
Pit or Below-grade Tank Application or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING				
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT			
PULL OR ALTER CASING	Multiple Completion CASING TEST AND CEMENT JOB			
OTHER:	OTHER:			
-				
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1. RUPU. Pull ESP equipment.				
2. Stimulate open hole 4194-4270 and perfs 4140-89 w/210 g Xylene, 3000 g 15% PAD acid.				
<ul> <li>3. Run Reda ESP equipment, 125 jts 2-7/8" tbg w/drain valve. Intake set @3823'.</li> <li>4. Install QCI wellhead connection.</li> </ul>				
<ul><li>4. Install QCI wellhead connection.</li><li>5. RDPU. Clean Location.</li></ul>				
5. RD1 6. Cloud Doubles.			/2 W 33	
Rig Up Date: 09/26/2005			8	2324
Rig Down Date: 09/27/2005		•		ું જ
			100	S &
			607	14.90/
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been will be				
constructed or closed according to NMOCD guideline	, a general permit	or an (attached) alternative	e OCD-approved	•
	, a general permit	plan		
SIGNATURE Kout	Fillet	TITLE Workover Com	pletion Specialist DATE	10/05/2005
TYPE OR PRINT NAME Robert Gill	pert E-mail address:	robert_gilbert@oxy.com	TELEPHONE NO.	505/397-8206
For State Use Only APPROVED BY	1) in h	TITLE	DATE	
CONDITIONS OF APPROVAL ANY:	WWK.	IIILE	DATE	
OC FIELD REPRESENTATIVE II/STAFF MANAGER OCT 1 3 2005				