

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-07145

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Continental-Wallace

8. Well Number

1

9. OGRID Number

227103

10. Pool name or Wildcat

Gladiola; Devonian (27740)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Platinum Exploration Inc

3. Address of Operator

550 W. Texas, Suite 500 Midland, TX 79701 432-687-1664

4. Well Location

Unit Letter N : 660 feet from the South line and 2310 feet from the West line
Section 6 Township 12-S Range 38-E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3875' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☒
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: Re-entry ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

07/21/05-08/03/05- Dig out WH cellar, weld 8 5/8" scab & weld 11" 3000# WH. Fill in cellar. PU swivel & drill @ 320'. Made 2'. WH broke. Dig out WH & re-weld collar. Fill cellar. RIH & tag @ 289', drill out to 607', circ cln. RIH to 1092', circ cln. RIH to 1824'. RU swivel & drill out paper & plastic. Wash to 4310'. Tag solid-displace hole w/280 bbls FW & test csg to 1000 psi-OK. Drill out metal & wood from 4310'-4340', circ cln. Drill out wood & metal from 4340-4350', drill out hard cmt from 4350' to top of 5 1/2 csg. Circ cln & POOH std back DC. NU BOP. RIH & tag top of csg @4428' & drill out cmt from 4428'-4480'. Fall out & circ cln, test csg to 1000 psi-OK. RIH to 5524', circ cln. RIH to 7617', drill out Reda bands & various metal to 7646' - stop making hole, circ cln & POOH. RIH & tag @7646'. Mill from 7646-7652 - fall out & circ cln. RIH to 12023', circ every 1000'. Attempt to cln out to TD with no success. Circ cln & POOH. RIH & tag @ 12023'. Mill from 12023-12026', circ cln. Mill from 12026-12027 & stop making hole, shoe plugged. POOH. RIH & tag @ 12027', mill to 12034', circ cln. POOH & LD DC. RIH w/5 1/2 HD pkr & set @ 11907'. Load & test csg to 1000 psi-OK. ND BOP - flange well. RD PU. WO on pump, facilities & electricity.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Gloria Holcomb TITLE Agent DATE _____

Type or print name Gloria Holcomb

E-mail address: gholcomb@t3wireless.com Telephone No. 432-687-1664

For State Use Only

PETROLEUM ENGINEER

APPROVED BY: [Signature] TITLE _____ DATE _____

Conditions of Approval (if any):

OCT 12 2005