

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION
320 South St. Francis Dr.
Santa Fe, NM 87505

OCT 17 2013

WELL API NO. 30-025-03194
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E7262
7. Lease Name or Unit Agreement Name Northeast Queen Unit
8. Well Number 15
9. OGRID Number 243874
10. Pool name or Wildcat PEARL QUEEN
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator QUANTUM RESOURCES MANAGEMENT, LLC	
3. Address of Operator 1400 MCKINNEY ST. SUITE 2400 HOUSTON, TX 77010	
4. Well Location Unit Letter F : 1650 feet from the N line and 2310 feet from the W line Section 23 Township 19S Range 35E NMPM LEA County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU RIG. NU BOP.
SET CIBP AT 4900'. CAP W/ 25 SX CEMENT
CIRCULATE HOLE W/ MUD LADEN FLUID
PERFORATE AT 3250'. SQZ W/ 25 SX. WOC AND TAG.
PERFORATE AT 1900'. SQZ W/ 25 SX. WOC AND TAG.
PERFORATE AT 380'. CIRCULATE CEMENT TO SURFACE
CUT OFF WELLHEAD AND INSTALL DRY HOLE MARKER.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bernie Montgomery TITLE Agent DATE 10-17-13


Type or print name Bernie Montgomery E-mail address: bernie@bernandassociates.com PHONE: 432-580-7161
For State Use Only

APPROVED BY: [Signature] TITLE Dist. Mgr. DATE 10-17-2013 M.
Conditions of Approval (if any):

OCT 17 2013

QUANTUM RESOURCES MGT, LLC
Northeast Pearl Queen Unit #15

CURRENT



8 5/8" @ 330' w/ 330 sx. Circ.

Perfs/OH 4945'-5038


4 1/2" @ 5029 w/ 200 sx. TOC unknown

TD 5038'

QUANTUM RESOURCES MGT, LLC
Northeast Pearl Queen Unit #15

PROPOSED

CUT OFF WELLHEAD & INSTALL DRY HOLE MARKER



8 5/8" @ 330' w/ 330 sx. Circ.

PERF AT 380'. CIRC CEMENT TO SURFACE.

PERF AT 1900'. SQZ W/ 25 SX. WOC AND TAG.

PERF AT 3250'. SQZ W/ 25 SX. WOC AND TAG.

Perfs/OH 4945'-5038

SET CIBP AT 4900'. CAP W/ 25 SX.

4 1/2" @ 5029 w/ 200 sx. TOC unknown

TD 5038'