

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

**RECEIVED**  
**HOBBS**  
**OIL CONSERVATION DIVISION**  
**1220 South St. Francis Dr.**  
**Santa Fe, NM 87505**

**OCT 31 2013**

WELL API NO. 30-025-09926
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: North Hobbs G/SA Unit
8. Well Number 421
9. OGRID Number 157984
10. Pool name or Wildcat Hobbs; Grayburg-San Andres
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3658' DF

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	2. Name of Operator Occidental Permian Ltd.
3. Address of Operator P.O. Box 4294, Houston, TX 77210-4294	4. Well Location Unit Letter <u>H</u> : <u>1650</u> feet from the <u>North</u> line and <u>330</u> feet from the <u>East</u> line Section <u>36</u> Township <u>18-S</u> Range <u>37-E</u> NMPM County <u>Lea</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3658' DF	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>
DOWNHOLE COMMINGLE <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/>
CASING/CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attached

Spud Date:

Rig Release Date:

hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Stephens TITLE Regulatory Compliance Analyst DATE 10/30/13  
Type or print name Mark Stephens E-mail address: Mark\_Stephens@oxy.com PHONE (713) 366-5158

For State Use Only

APPROVED BY [Signature] TITLE Det. MGT DATE 10-31-2013  
Conditions of Approval (if any):

**OCT 31 2013**

North Hobbs G/SA Unit Well No. 421  
API No. 30-025-09926

Subject well plugged and abandoned as follows -

10/25/13---RIH W/WORKSTRING - TAG CIBP @ 3988' - CIRC WELL W/100 BBL OF MLF. SPOT 25 SXS @ THAT POINT WILL TAG PLUG ON MONDAY- LEFT TOP OF CMT @ 3749'.

10/28/13---RIH TAG PLUG @ 3739' - TEST CASING- TESTED GOOD W/ 400 PSI - PUH TO 2830' SPOT 30 SXS @ THAT POINT NO WOC OK BY MARK W. W/O.C.D. PUH TO 1430'. RU WIRELINE RIH PERF @ 1720' ESTABLISH PUMP RATE @ 800 PSI @ 1BBL MIN - SQZ 50 SXS INTO PERFS WOC 4 HRS. RIH TAG PLUG @ 1570'. PUH TO 425' PERF @ THAT POINT. ESTABLISH PUMP RATE 700 PSI @ 1½ BBL MIN SQZ 40SXS NEVER GOT. RETURN ON SURFACE DISPLACE TO 300' OK BY MARK W. W/ OCD WOC WILL TAG IN MORNING

10/29/13---RIH TAG PLUG @ 260'. CALLED MARK OK TO PERF @ 60' - RIH W/WIRELINE PERF @ 60' ESTABLISH PUMP RATE 1 ½ BBL @ 900 PSI NO RETURN ON SURFAC TALK TO MARK OK TO BULLHEAD SQZ 25 SXS INTO PERFS. FILL UP 5½ W/ 35 SXS.

RD x MO x clean location.

