Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 HOB	BS OCD OIL CONSERVATION DIVISION 1220 South St. Francis Dr	WELL API NO.
District II – (5/5) /48-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-37829 5. Indicate Type of Lease
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 874 NOV	2012 1220 South St. Francis Dr.	STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 874 100 V 1 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	•	0. 0 0 0 0 0 0
87505 REC	EVED PEROPES ON WELLS	7.1
	STAND REPORTS ON WELLS LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name GRIZZELL B
	TION FOR PERMIT" (FORM C-101) FOR SUCH	GRIZZEEL B
PROPOSALS.)	a (w. n. 🗖 o.i	8. Well Number 8
	Gas Well Other	,
2. Name of Operator VANGUARD PERMIAN LLC		9. OGRID Number 258350
3. Address of Operator		10. Pool name or Wildcat
P O BOX 1570 281 NORTH NM HIG	GHWAY 248, EUNICE, NM 88231	PENROSE SKELLY GRAYBURG
4. Well Location		
Unit Letter H :	2310 feet from the NORTH line and	197 feet from the EAST line
Section 8 Township 22S Range 37E NMPM LEA County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
	3420 KB	
the product of the section of the se		
12 Check An	propriate Box to Indicate Nature of Notice,	Report or Other Data
12. Check Ap	propriate box to indicate readure of reduce,	Report of Other Data
NOTICE OF INT	ENTION TO: SUB	SEQUENT REPORT OF:
	PLUG AND ABANDON REMEDIAL WOF	
TEMPORARILY ABANDON	CHANGE PLANS 🔲 COMMENCE DR	ILLING OPNS. ☐ P AND A ☐
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMEN	Т ЈОВ □
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM		
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
MIRU PU AND UNHANG WELL, PULL OUT PRODUCTION EQUIPMENT, MAKE CLEANOUT RUN WITH BIT AND		
SCRAPER. SET RBP AND PERFORATE GRAYBURG AT 3656-3660, 3774-3780. FRAC W/87,020 LBS OF PROPANT.		
CLEAN OUT WELL TO RBP AND PUT WELL ON PRODUCTION.		
RETURN TO PROD. 24 HRS TEST O		
	,	·
	OPERATOR HAS NOT FILED A F	O DISCLOSURE
	T FILED AF	RAC
	TATOR HAS NOT THE	•
	OPERATOR TO THE FORM ONLINE	
Spud Date:	FORM	
Spud Date.		
I hereby certify that the information ab	ove is true and complete to the best of my knowleds	ge and helief
i nereby certify that the information ab	ove is true and complete to the best of my knowledg	ge and benef.
oh U	1	. 1-1
SIGNATURE SMY HEAR	title_agent	DATE 11/7/13
	E-mail address: _gheard@oilreportsinc.com_	PHONE: 575-393-2727
For State Use Only		
APPROVED BY: Maley & Brown TITLE Compliance Officer DATE 11/13/2013		
Conditions of Approval (if any):		
Tomations of Approviation (it and).		
		(
		NO. 4 4 0040
		NOV 1 4 2013
		•