

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

Revised August 1, 2011

JAN 10 2014

RECEIVED

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-26015 ✓
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Vanguard Permian LLC ✓		6. State Oil & Gas Lease No.
3. Address of Operator 5847 San Felipe St. Ste. 3000, Houston, TX 77057		7. Lease Name or Unit Agreement Name New Mexico M State ✓
4. Well Location Unit Letter J : 2160 feet from the South line and 2310 feet from the East line Section 18 Township 22S Range 37E NMPM County Lea		8. Well Number 49 ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3427'		9. OGRID Number 227588
		10. Pool name or Wildcat Eunice-San Andres, Southwest

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

A closed loop system will be used for all fluids from this wellbore and disposed of required by ocd rule 19.15.17.

1. Notify OCD 24 hrs prior to commencement of P & A
2. MIRU P & A equip. NDWH NUBOP RIH w/ 2 3/8 ws tag cibp @ 3745'
3. Circ hole w/MLF min 9lb bw w/25 lbs gel p/bbl
4. Spot 35x "c" cmt on top of cibp 3745'-3500' (San Andres perms, bottom salt)
5. Perf @ 1300' circ cmt to surf behind 5 1/2" csg, displace to 1000' in 5 1/2" woc & tag (top of salt 8 5/8" shoe, rustler)
6. Spot 40x "c" cmt from 350'-surf (water & surf protection)
7. Cut off well heads, Install dry hole marker, clean location

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Jimmy Bagley

TITLE

Agent

DATE

1/7/14

Type or print name

Jimmy Bagley

E-mail address: sunsetwellservice@yahoo.com

PHONE:

432-561-8600

For State Use Only

APPROVED BY:

Mary Brown

TITLE

Compliance Officer

DATE

1/14/2014

Conditions of Approval (if any):

OIL CONSERVATION DIVISION - Hobbs office **Must Be Notified**
24 hours prior to the beginning of Plugging Operations.

JAN 14 2014