
	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-encoded to abandoned well. Use Form 3160-3 (APD) for such proposals.			NMLC032096A 6. If Indian, Allottee or Trib	NMLC032096A 6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE – Other instructions on page 2.			7. If Unit of CA/Agreement WBDU 120042X	7. If Unit of CA/Agreement, Name and/or No. WBDU 120042X	
1. Type of Well Gas We	ell 🔽 Other WSW	8. Well Name and No. West Blinebry Drinkard U	8. Well Name and No. West Blinebry Drinkard Unit (WBDU) #67		
2. Name of Operator Apache Corporation (873)			9. API Well No. 30-025-06639	9. API Well No. 30-025-06639	
3a. Address 303 Veterans Airpark Lane, Suite 3000 Midland, TX 79705	Phone No. (include area code) 2/818-1062		10. Field and Pool or Exploratory Area WSW; San Andres (96221)		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 660' FNL & 660' FEL, Sec. 17, T21S, R37E			11. Country or Parish, State Lea County, NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA					
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION				
✓ Notice of Intent	Acidize	Deepen Fracture Treat	Production (Start/Resume)	Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed only as following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Apache intends to work on and possibly squeeze this well, due to a suspected casing leak. The well began to build pressure on the 7" production casing/3.5" tubing annulus above normally observed levels, indicating gas influx into the wellbore. Pressure was measured on the bradenhead of the 9-5/8" intermediate casing (the annular space between the 9-5/8" and the 7" casing and the annular space between production hole and the 7" casing) to be equalized with that of the 7" production casing/3.5" tubing annulus, indicating a leak has developed in the 7" production casing. Estimated cement top in the well, run in with a retrievable bridge plug and packer, and attempt to locate the suspected casing leak (s). Any leaks that are located will be cement squeezed under a retainer, the casing pressure tested after cement drill out, and the well returned to production. 14. Thereby certify that the foregoing is true and correct. Name (<i>Printed/Typed</i>)					
Reesa Holland Fisher		Title Sr. Staff R	Title Sr. Staff Reg Tech		
Signature Relesa 76	ihan	Date 12/19/2013	ΔΙ	PROVED	
	THIS SPACE FO	R FEDERAL OR STA			
Approved by Conditions of approval, if any, are attached that the applicant holds legal or equitable ti entitle the applicant to conduct operations to Title 18 U.S.C. Section 1001 and Title 43 U	Date	AN 1 0 2014 SI Chris Walls J OF LAND MANAGEMENT ALSBAD FIFI D OFFICE gency of the United States any false,			
fictitious or fraudulent statements or repres (Instructions on page 2)		Its jurisdiction.	JAN 2	1 2014	



Conditions of Approval

Apache Corportation WBDU 67 API 3002506639

- 1. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 2. Surface disturbance beyond the existing pad shall have prior approval.
- 3. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 4. Functional H_2S monitoring equipment shall be on location.
- 5. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. After squeezing the casing leak, perform a BLM PET witnessed (charted) casing integrity test of 500 psig. Pressure leakoff may require correction for approval. Include a copy of the chart in the subsequent sundry for this workover.
- 7. File intermediate **subsequent sundry** Form 3160-**5** within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.

Well with a Packer - Operations

- 1) Conduct a Mechanical Integrity Test of the tubing/casing annulus after a tubing, packer or casing seal is established. Repair that seal any time more than five barrels of packer fluid is replaced within 30 days.
- 2) The minimum test pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with minimum 200 psig differential between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need to be reduced). An alternate method for a BLM approved MIT is to have the fluid filled system open to atmospheric pressure and have a loss of less than five barrels in 30 days witnessed by a BLM authorized officer.
- 3) Document the pressure test on a one hour full rotation calibrated recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict injection approval.

- Make arrangements 24 hours before the test for BLM to witness. In Lea County phone 575-393-3612. If no answer, 'leave a voice mail or email with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.
- 5) Submit a subsequent Sundry Form 3160-5 relating the MIT activity. Include a copy of the recorded MIT pressure chart. List the name of the BLM witness, or the notified person and date of notification. NMOCD is to retain the original recorded MIT chart.
- 6) Use of tubing internal protection, tubing on/off equipment just above the packer, a profile nipple, and an in line tubing check valve below the packer or between the on/off tool and packer is a "Best Management Practice". The setting depths and descriptions of each are to be included in the subsequent sundry. List (by date) descriptions of daily activity of any previously unreported wellbore workover.
- 7) Submit the original subsequent sundry with three copies to BLM Carlsbad.
- 8) Compliance with a NMOCD Administrative Order is required, submit documentation of that authorization.
 - a) Approved injection pressure compliance is required.
 - b) If injection pressure exceeds the approved pressure you are required to reduce that pressure and notify the BLM within 24 hours.
 - c) When injection pressure is within 50 psig of the maximum pressure, install automation equipment that will prevent exceeding that maximum. Submit a subsequent report (Sundry Form 3160-5) describing the installed automation equipment within 30 days.
- 9) Unexplained significant variations of rate or pressure to be reported within 5 days of notice.
- 10) The casing/tubing annulus is required to be monitored for communication with injection fluid or loss of casing integrity. A BLM inspector may request verification of a full annular fluid level at any time.
- 11) A "Best Management Practice" is to maintain the annulus full of packer fluid at atmospheric pressure. Equipment that will display on site, continuous open to the air fluid level is necessary to achieve this goal.
- 12) Loss of packer fluid above five barrels per month indicates a developing problem. Notify BLM Carlsbad Field Office, Petroleum Engineering within 5 days.
- 13) A suggested format for monthly records documenting that the casing annulus is fluid filled is available from the BLM Carlsbad Field Office.
- 14) Gain of annular fluid requires notification within 24 hours. Cease injection and maintain a production casing pressure of 0 psia. Notify the BLM's authorized officer ("Paul R. Swartz" <<u>pswartz@blm.gov></u>, cell phone 575-200-7902). If there is no response phone 575-361-2822.
- 15) Submit a (Sundry Form 3160-5) subsequent report (daily reports) describing all wellbore activity and Mechanical Integrity Test as per item 1) above. Include the date(s) of the well work, and the setting depths of installed equipment: internally corrosive protected tubing, tubing on/off equipment just above the packer, and an in line tubing check valve below the packer or between the on/off tool and packer. The setting depths and descriptions of each are

to be included in the subsequent sundry. List daily descriptions of any previously unreported wellbore workover(s) and reason(s) the well annular fluid was replaced.

CRW 010813

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.