

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88241
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

HOBBS OGD

JAN 21 2014

RECEIVED

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-04436
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other WIW		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Mar Oil and Gas Corporation		6. State Oil & Gas Lease No.
3. Address of Operator PO Box 5155 Santa Fe, NM 87502		7. Lease Name or Unit Agreement Name Eumont Hardy Unit
4. Well Location Unit Letter A : 660 feet from the North line and 660 feet from the East line Section 1 Township 21S Range 36E NMPM Lea County		8. Well Number 031
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 151228
		10. Pool name or Wildcat Eumont; Yates, 7 Rivers, Queen

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: **Convert to oil prod** ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

All well fluids with be circulated to steel pit x No earthen pit will be constructed x any solids will be hauled to Sundance
Mar proposes to pull existing injection tubing and packer
Clean out well as necessary
Run production equipment
Convert well to oil production

**PROVIDE CURRENT WELLBORE DIAGRAM
WITH SUBSEQUENT C-103**

**AFTER RETURNING THIS WELL TO PRODUCTION;
OCD requires form C-103 with dates and discription
of work done. Also form C-104 with Transportors,
Perfs producing from, Tubing size & Depth, and
24 hour production test.**

Release Date:

The form C-105 is also required.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Billy E. Prichard TITLE Foreman DATE 1/14/14
Type or print name Billy E. Prichard E-mail address: billy@pwllc.net PHONE: 4329347680
For State Use Only
APPROVED BY: Mary G. Brown TITLE Compliance Officer DATE 1/22/2014
Conditions of Approval (if any):

JAN 23 2014