

Submit 3 Copies To Appropriate District  
 Office  
 District I  
 1625 N. French Dr., Hobbs, NM 87240  
 District II  
 1301 W. Grand Ave., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM  
 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 June 19, 2008

HOBBS OCD

OIL CONSERVATION DIVISION

JAN 24 2014

1220 South St. Francis Dr.  
 Santa Fe, NM 87505

RECEIVED

WELL API NO. 30-025-31674
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Arrowhead Grayburg Unit
8. Well Number #226
9. OGRID Number 005380
10. Pool name or Wildcat Arrowhead, Grayburg
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
 Oil Well  Gas Well  Other

2. Name of Operator  
 XTO Energy, Inc.

3. Address of Operator  
 200 N. Loraine, Ste. 800 Midland, TX 79701

4. Well Location  
 Unit Letter H : 1650 feet from the North line and 560 feet from the East line  
 Section 13 Township 22S Range 36E NMPM County Lea

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENT  
 PERFORM REMEDIAL WORK  
 TEMPORARILY  
 PULL  
 OTH  
 Approved for Plugging of well bore only.  
 Liability under bond is retained pending receipt of  
 C-103 (Specifically for Subsequent Report of Well  
 Plugging) which may be found at OCD web page  
 under forms/  
 www.emnrd.state.nm.us/oecd

SUBSEQUENT REPORT OF:

REMEDIAL WORK  ALTERING CASING   
 COMMENCE DRILLING OPS  P AND A   
 CASING/CEMENT JOB   
 OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

01/07/2014: MIRU PU. Set CIBP @ 3600'. Tag CIBP @ 3600'.  
 01/08/2014: Press TCA to 500psi w/no loss. Spot 25sx 'C' cmt on CIBP @ 3600'. PUH to 2733'. Spot 45sx 'C' cmt. PUH to 1311'. Spot 30sx 'C'. Tag TOC @ 1071'. Ok to proceed, per M. Whitaker (NMOC). PUH to 200'. Spot 25sx 'C' to surf. RDMD PU. Cut off WH & Anchors, install dry hole marker.

Spud Date:  Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stephanie Rabadue TITLE Regulatory Analyst DATE 01/15/2014  
stephanie\_rabadue@xtoenergy.com  
 Type or print name Stephanie Rabadue E-mail address: stephanie\_rabadue@xtoenergy.com PHONE 432.620.6714

For State Use Only  
 APPROVED BY Mark Whitaker TITLE Compliance Officer DATE 01-27-2014  
 Conditions of Approval (if any):

JAN 27 2014