

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87401
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 October 13, 2009

HOBBS OCD
 JAN 31 2014
 RECEIVED

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-37792
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name SEVEN RIVERS QUEEN UNIT
8. Well Number: 080
9. OGRID Number 269324
10. Pool name or Wildcat EUNICE;SEVEN RIVERS-QUEEN, SOUTH

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other Injection

2. Name of Operator
LINN OPERATING, INC.

3. Address of Operator
600 TRAVIS, SUITE 5100, HOUSTON, TEXAS 77002

4. Well Location
 Unit Letter F 1430 feet from the N line and 1384 feet from the W line
 Section 27 Township 22S Range 36E NMPM LEA County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3,506'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENT TO PERFORM REMEDIAL WORK TEMPORARILY
 Approved for plugging of well bore only. Liability under bond is retained pending receipt of Report of Well Plugging (Specifically for Subsequent Report of Well Plugging) which may be found at OCD web page www.emnrd.state.nm.us/oecd under forms/

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPNS. P AND A
 CASING/CEMENT JOB

OTHER: **ON ACOI LIST**

Completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of completion or recompletion.

Completed Plugging and Abandoning Operations.

1/7/14 - MIRU plugging equipment. Dug out cellar. NDWH. NU BOP. RIH w/ gauge ring to 3650'. POH.

1/8/14 - RIH w/ 5-1/2 CIBP on tbg & set @ 3,600'. Circ hole w/ 84 bbls of mud laden fluid. Spotted 25 sx cmt @ 3600-3347'. POH w/ tbg. Pressure tested csg to 500 psi. Held. Spotted 30 sx cmt @ 3150-2847. POH w/ tbg to 1600'. Spotted 30 sx cmt @ 1600-1297. POH w/ tbg. ND BOP. Cut off WH. RIH w/ tbg to 411'. Spotted 50 sx cement @ 411 - surface. RD and moved off.

1/9/14 - Moved in welder. Welded on plate and welded on "Above Ground Dry Hole Marker". Backfilled cellar, removed deadman, cleaned location and moved off.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry Callahan TITLE: REGULATORY COMPLIANCE SPECIALIST III DATE January 30, 2014

Type or print name TERRY B. CALLAHAN E-mail address: tcallahan@linnenergy.com PHONE: 281-840-4272

For State Use Only

APPROVED BY: Mark White TITLE Compliance Officer DATE 02/03/2014

Conditions of Approval (if any):

FEB 03 2014

dn