Submit 1 Copy To Appropriate District	State of New Me		Form C-103
<u>District I</u> – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240		ral Resources	Revised July 18, 2013 WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		DIVISION	30-025-03215 5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Francis Dr.		STATE FEE S	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.
87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			East Pearl Queen Unit
1. Type of Well: Oil Well Gas Well Other Injection Well			8. Well Number 28
2. Name of Operator State of NM formerly Xeric Oil & Gas Corp.		9. OGRID Number	
3. Address of Operator		10. Pool name or Wildcat	
1625 N French Drive Hobbs, NM 88240		Pearl Queen	
4. Well Location			
Unit Letter H: 1980 feet from the North line and 660 feet from the East line Section 27 Township 19S Range 35E NMPM County Lea			
Section 27 Township 19S Range 35E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
Section (Show meller Dit, All b), KI, GR, etc.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☑ PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT JOB ☐			
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM	_		_
OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
5-28-13 MIRU Basic Plugging Services.			
5-29-13 Tag CIBP at 4595'. Spot 25 sx cmt. WOC.			
5-30-13 Tag at 4206'. POOH to 3400'. Spot 25 sx cmt. POOH to 1800'.			
Spot 25 sx cmt. WOC.			
5-31-13 Tag at 1450'. POOH to 355'. Fill to surface w/ cmt. RDMO.			
Install dry hole marker.			
The call all more marker.			
			· ·
Spud Date:	Rig Release Da	te:	
	, , , , , , , , , , , , , , , , , , , ,		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
Thereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Much Little touplisher Officer DATE 02/13/2014			
Type or print name E-mail address: PHONE:			
For State Use Only A A			
APPROVED BY: Maley Srown TITLE Compliance Office Date 2/14/2014			
Conditions of Approval (if any):			
V			R '