State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-200

FILE IN TRIPLICATE CONSEDVATION DIVISION	Revised 5-27-2004
DISTRICT 1 DISTRI	WELL API NO.
FILE IN TRIPLICATE DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 DISTRICT II 1301 W. Grand Ave. Artesia. NM 88210	30-025-28411
DISTRICT II	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410	STATE X FEE
DISTRICT III RECEIVE	6. State Oil & Gas Lease No.
	7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 33
1. Type of Well:	8. Well No. 142 Z /
Oil Well Gas Well Other Injector	
Name of Operator Occidental Permian Ltd.	9. OGRID No. 157984
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323 4. Well Location	· /
	From The West Line
Section 33 Township 18-S Range 38-E	NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.)	
3635' GL	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	T JOB
OTHER: Coiled tubing	gjob
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
1. RU coiled tubing unit.	
2. RIH and clean out to 4295'. Pull up to 4050'. Ran perf clean tool and water wash perfs @4067-4237'.	
3. Pump 10 bbl gel sweep.	
4. Wash perfs from 4067-4237' w/2500 gal of 15% NEFE acid.5. Pump 10 bbl gel sweep. Circulate clean.	
6. POOH and RD coiled tubing unit.	
7. Return well to injection.	
RU 11/26/2013	
RD 11/26/2013	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or	
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved	
SIGNATURE DATE 02/13/2014	
TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com	Associate DATE 02/13/2014 TELEPHONE NO. 806-592-6280
For State Use Only	500-342-0280
APPROVED BY Value Stown TITLE Complian	100 / 2/20/2016
CONDITIONS OF APPROVAL IF ANY	10, CAPTELL DATE 2/2012019

FER 20 2014