HOBBS OCD State of New Mexico Energy, Minerals and Natural Resources Department

FILE IN TRIPLICATE	FEB 2 8 20 FEB	TION DIVISION	Revised 5-27-2004
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240	1220 South 5	St. Francis Dr. NM 87505	WELL API NO. 30-025-07599 —
DISTRICT II	RECEIVED		5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210	-		STATE FEE X
<u>DISTRICT III</u>			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410			
SUNDRY NO	TICES AND REPORTS ON WEI	LLS	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "/	ROPOSALS TO DRILL OR TO DEEPEN APPLICATION FOR PERMIT" (Form C-1)		South Hobbs (G/SA) Unit 🖌
Type of Well: Oil Well	Gas Well Other Inj	ector	8. Well No. 34
2. Name of Operator Occidental Permian Ltd,	~		9. OGRID No. 157984
3. Address of Operator			10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 4. Well Location	79323		
Unit Letter H : 1980 Feet From The North Line and 660 Feet From The East Line			
Section 4	Township 19-S	Range 38-E	NMPM Lea County
Section 4	11. Elevation (Show whether DF, RK		
	3617' DF		
Pit or Below-grade Tank Application or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INT	ENTION TO:	SUBS	EQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			
	CHANGE PLANS	COMMENCE DRILLING OPN	IS. PLUG & ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	Т ЈОВ
OTHER:		OTHER: Coiled tubing	ziob X
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
1. RU coiled tubing unit.			
2. RIH and clean out to 4197'. Pull up to 4060'. Ran perf clean tool and water wash perfs 4070-4197'.			
3. Pumped 10 bbl gel sweep.			
 Wash perfs from 4070-4197' w/ 2500 gal of 15% NEFE acid. Pump 10 bbl gel sweep. Circulate clean. 			
6. POOH and RD coiled tubing unit.			
7. Return well to injection.			
RU 02/21/2014			
RD 02/21/2014			
I hereby certify that the information above is	true and complete to the best of my knowl	edge and belief. I further certify the	hat any pit or below-grade tank has been/will be
constructed or			
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan			
made .	Allow	- ·	
SIGNATURE	UXPINION -	TITLE Administrative A	Associate DATE <u>02/27/2014</u>
TYPE OR PRINT NAME Mendy A.J	ohnson E-mail address:	mendy_johnson@oxy.com	TELEPHONE NO. 806-592-6280
For State Use Only	P.L.	(m. alia	ARC ASIATIZANA
APPROVED BY Wann With TITLE Ungsudue Uffler DATE USO 1/2014			
CONDITIONS OF APPROVAL IF ANY:		V	
			4 B
			MAR 1 0 2014
			NIWIN WW