Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-35555
District II - (575) 748-1283 811 S. First St., Artesia, NM 882490BBS OCD OIL CONSERVATION DIVISION District III - (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease
District III – (505) 334-6178 1220 South St. Francis Dr.	STATE FEE
District IV = (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 SINDRY NOTICE OF PEROPTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
OD NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Section 24
1. Type of Well: Oil Well Gas Well Other	8. Well Number
	614
2. Name of Operator	9. OGRID Number: 157984
Occidental Permian Ltd. 3. Address of Operator	10. Pool name or Wildcat
2611 State Hwy 214 Denver City, TX 79323	Hobbs (G/SA)
4. Well Location	1110000 (0, 0.12)
Unit Letter G: 2140 feet from the North line and 1542	feet from the East line
Section 24 Township 18S Range 37E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
3669' GL	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO:	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐	
<u> </u>	ILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	•
DOWNHOLE COMMINGLE	
	· · · · · · · · · · · · · · · · · · ·
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	impletions. Attach welloofe diagram of
During this procedu	ure we plan to use
1. RUPU and POOH W/ESP equipment the closed-loop sys	
2. RIH W/bit and tag for fill, CO if necessary tank and haul contents to the required	
3. Treat for conditions4. Run ESP equipmentdisposal per ODC R	ule 19.15.17
4. Run ESP equipment5. RDPU and clean location	
3. Test o and clean foculon	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowleds	re and helief
increase certify that the information above is true and complete to the best of my knowledge.	ge and benefit
$I \vdash \langle a \rangle \cap \langle a \rangle$	
SIGNATURE STEWE MORE TITLE Lift Specialist	DATE 3/18/2014 .
Type or print name Steve Snead E-mail address: steve_snead@ox	<u>y.com</u> PHONE: <u>806-592-6312</u>
For State Use Only	·
APPROVED BY: Mach Whitch TITLE Compliance of	FIGO DATE 03/21/2014
APPROVED BY: Mach Whiteham TITLE Who Library:	DATE SILITION
Conditions of Approval (it airs).	
	MAR 2 4 201
	LIAK : & & TO No
	/