	Submit 1 Copy To Appro Office		State of New Mexico		Form C-103		
	District I - (575) 393-616		Minerals and Nat	nerals and Natural Resources		Revised July 18, 2013	
	1625 N. French Dr., Hobb <u>District II</u> – (575) 748-12			A DIVIGION	WELL API NO. 30-025-35297		
	811 S. First St., Artesia, 1 District III – (505) 334-6	NM 88210 HOBBS COAL C	AL CONSERVATION DIVISION		5. Indicate Type of STATE	of Lease	
	1000 Rio Brazos Rd., Az			South St. Francis Dr.		FEE	
	<u>District IV</u> – (505) 476-3- 1220 S. St. Francis Dr., S	460 MAR 2 0 ZUI4	2 6 2014 Santa Fe, NM 87505		6. State Oil & Ga B-9385	s Lease No.	
	87505	CLD IDDU NOTICES AND REPORTS ON WELLS				II. '/ A	
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or U (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A						Unit Agreement Name	
	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				New Mexico "AN	N" State	
	PROPOSALS.) 1. Type of Well: O	ROPOSALS.) Type of Well: Oil Well Gas Well Other				19	
/	2. Name of Operator 9. OGRID Number 2 13 190						
CrownQuest Operating, LLC 3. Address of Operator MAR 2 4 2014 10. Pool name or Wildcat							
		STE 500 Midland, TX 79710)	/	Saunders Permo U		
4. Well Location RECEIVED							
	Unit LetterF_:1980_feet from theNorth line and1980feet from theWestline						
	Section 22 Township 14S Range 33E NMPM Lea County						
		11. Elevatio	n (Show whether Di	R, RKB, RT, GR, etc.)			
	12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A					<u> </u>		
						ALTERING CASING PAND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE / Jean extension CLOSED-LOOP SYSTEM TAKES OTHER:							
	13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimate of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.						
Drogadura:							
	Procedure: 1. Rig up pump truck						
	 Load and test CIBP and casing to 550 psig for 30 minutes. 						
] .				
	Spud Date:		Rig Release D	Pate:			
			1				
-	I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
	nervey verify that the information above is true and complete to the best of my knowledge and benefit.						
	SIGNATURE /		TITLE Le	ase Manager	DA	TE 3/24/2014	
	SIGNATURE	D. J. Marin					
	Type or print name	Brandon Willis	E-mail addres	ss: bwillis@crov	vnquest.com _{PH}	ONE: 432-528-9830	
	For State Use Only	0					
	APPROVED BY:	Lel Sernama	L TITLE S	Laff Wanage	er DA'	TE 3.26/14	
	Conditions of Approv	val (if any):				<u>-</u>	