

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

HOBBS OGD

Energy, Minerals and Natural Resources

APR 28 2014

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

RECEIVED

Form C-103

Revised July 18, 2013

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-23089
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other SWD		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Kevin O Butler & Assoc, Inc		6. State Oil & Gas Lease No. 002404
3. Address of Operator 550 W Texas, Suite 660, Midland, TX 79702		7. Lease Name or Unit Agreement Name Maxwell
4. Well Location Unit Letter <u>E</u> : 2310 feet from the <u>North</u> line and <u>990</u> feet from the <u>West</u> line Section <u>6</u> Township <u>13S</u> Range <u>38E</u> NMPM County <u>Lea</u>		8. Well Number 002
11. Elevation (Show whether DR, RKB, RT, GR, etc.) GL 3964		9. OGRID Number 12627
		10. Pool name or Wildcat Wolfcamp, Penn, Miss. Devonian

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: RE-PERF & ACIDIZE ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Objective: To increase injectivity by adding and re-perforating and re-acidizing.

Rig up well service unit. NU BOP.

Unset and pull packer and stand PC tubing in derrick.

Tally and pu bit, bs, and work string (test tubing).

RU reverse unit and clean out well to top of CIBP at 9803'. Circ hole clean. RD reverse unit.

RU wire line and re-perf the Wolfcamp zone 4spf: 9624'-9642', 9660'-9680', 9700'-9720'.

TIH with Model R packer and work string. Acidize above perf with 5000 gal. 20% acid in 3 stages.

TOH and LD work string.

TIH with NC packer and PC tubing.

Circ packer fluid, set packer. Notify OCD 24 hrs before MIT.

RD clean location

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Mary S Brown

TITLE

DATE 4/28/14

Type or print name M.Y. Merchant

E-mail address: mymerchant@pennacoil.com

PHONE: (505) 492-1236

For State Use Only

APPROVED BY:

Mary S Brown

TITLE

Dist. Supervisor

DATE

4/29/2014

Conditions of Approval (if any):

APR 29 2014