Office RIODRE COR	State of New Mexico	Form C-103		
	y, Minerals and Natural Resor	urces August 1, 2011	_	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-025-28813	-	
811 S. First St., Artesia, NM 8821 MAY U 5 ZUWIL	CONSERVATION DIVISI	ON 5. Indicate Type of Lease	┪	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE ☐ FEE ☒		
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No. 026458		
SUNDRY NOTICES AND I		7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRIID DIFFERENT RESERVOIR. USE "APPLICATION FOR PROPOSALS.)				
1. Type of Well: Oil Well  Gas Well	Other	8. Well Number 1		
2. Name of Operator		9. OGRID Number		
Lynx Operating Co., Inc.		175701	$\downarrow$	
3. Address of Operator 600 N. Marienfeld, Ste. 918, Midland, TX 79	701	10. Pool name or Wildcat		
4. Well Location	70.1	Denton Wolfcamp	$\downarrow$	
	and from the South 15-	and CCO Seat Security Park 110		
		e and 660 feet from the East line	1	
	vnship 15-S Range 37-E ion (Show whether DR, RKB, RT	NMPM County Lea	754	
3778 GR	ioii (Snow whether DR, KKB, KI	, GR, etc.)	Y	
			83.	
12 Check Appropriat	e Box to Indicate Nature of	Notice, Report or Other Data		
** *		Trottee, Report of Other Batta		
NOTICE OF INTENTION		SUBSEQUENT REPORT OF:		
		IAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE		ENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING   MULTIPLI DOWNHOLE COMMINGLE	E COIVIPL	G/CEMENT JOB		
DOWN TOLL COMMITTEEL		•		
OTHER:	□ OTHER		_	
		details, and give pertinent dates, including estimated dat	te	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.	03/21/14 I ay down rods and r	oump. Dug out cellar. 03/24/14 ND wellhead and		
		eaned out to 9134'. 04/02/14 Circulated hole w/		
		04/03/14 Tagged plug @ 8900'. Shut down for		
wind. 04/04/14 Set packer @ 4000'. Pressure tested 5 1/2 csg to 500 psi. Held. Perf'd csg @ 6750'. Pressured up on				
perfs to 500 psi. POH w/ packer. RIH and spotted 25 sx class C cement @ 6800-6547. POH. WOC. NO Tag. Re-spotted				
	C. 04/08/14 NO Tag. Re-Spott	ed 25 sx cement @ 6800-6547. WOC. Tagged plug		
	C. 04/08/14 NO Tag. Re-Spott let packer @ 4500'. Pressured u	ed 25 sx cement @ 6800-6547. WOC. Tagged plug on csg. Pulled packer and spotted 25 sx		
cement@ 4800-4547. POH. 04/09/14	C. 04/08/14 NO Tag. Re-Spott fet packer @ 4500'. Pressured t Tagged plug @ 4650'. POH w/	ed 25 sx cement @ 6800-6547. WOC. Tagged plug up on csg. Pulled packer and spotted 25 sx tbg. Rigged up casing jacks. Pulled stretch. Cut		
cement@ 4800-4547. POH. 04/09/14 casing @ 3200'. POH w/ casing. 04/10	C. 04/08/14 NO Tag. Re-Spott set packer @ 4500'. Pressured u Tagged plug @ 4650'. POH w/ 0/14 RIH w/ tbg and spotted 30	ed 25 sx cement @ 6800-6547. WOC. Tagged plug on csg. Pulled packer and spotted 25 sx		
cement@ 4800-4547. POH. 04/09/14 casing @ 3200'. POH w/ casing. 04/10 WOC. Tagged plug @ 3100'. Spotted	C. 04/08/14 NO Tag. Re-Spott set packer @ 4500'. Pressured u Tagged plug @ 4650'. POH w/ 0/14 RIH w/ tbg and spotted 30 35 sx @ 2100-1971. WOC. Tag	ed 25 sx cement @ 6800-6547. WOC. Tagged plug up on csg. Pulled packer and spotted 25 sx tbg. Rigged up casing jacks. Pulled stretch. Cut sx cement @ 3250-3090. Pulled out of cement.		
cement@ 4800-4547. POH. 04/09/14 casing @ 3200'. POH w/ casing. 04/10 WOC. Tagged plug @ 3100'. Spotted	C. 04/08/14 NO Tag. Re-Spott set packer @ 4500'. Pressured u Tagged plug @ 4650'. POH w/ 0/14 RIH w/ tbg and spotted 30 35 sx @ 2100-1971. WOC. Tag	ed 25 sx cement @ 6800-6547. WOC. Tagged plug up on csg. Pulled packer and spotted 25 sx tbg. Rigged up casing jacks. Pulled stretch. Cut sx cement @ 3250-3090. Pulled out of cement. gged plug @ 2000'. Spotted 35 sx cement @ 440-		
cement@ 4800-4547. POH. 04/09/14 casing @ 3200'. POH w/ casing. 04/10 WOC. Tagged plug @ 3100'. Spotted 311. POH. WOC. 04/11/14 No Tag. F	C. 04/08/14 NO Tag. Re-Spott fet packer @ 4500'. Pressured u Tagged plug @ 4650'. POH w/ 0/14 RIH w/ tbg and spotted 30 35 sx @ 2100-1971. WOC. Tag Re-Spotted 35 sx @ 440. WOC.	ed 25 sx cement @ 6800-6547. WOC. Tagged plug up on csg. Pulled packer and spotted 25 sx tbg. Rigged up casing jacks. Pulled stretch. Cut sx cement @ 3250-3090. Pulled out of cement. gged plug @ 2000'. Spotted 35 sx cement @ 440-		
cement@ 4800-4547. POH. 04/09/14 casing @ 3200'. POH w/ casing. 04/10 WOC. Tagged plug @ 3100'. Spotted	C. 04/08/14 NO Tag. Re-Spott set packer @ 4500'. Pressured u Tagged plug @ 4650'. POH w/ 0/14 RIH w/ tbg and spotted 30 35 sx @ 2100-1971. WOC. Tag	ed 25 sx cement @ 6800-6547. WOC. Tagged plug up on csg. Pulled packer and spotted 25 sx tbg. Rigged up casing jacks. Pulled stretch. Cut sx cement @ 3250-3090. Pulled out of cement. gged plug @ 2000'. Spotted 35 sx cement @ 440-		
cement@ 4800-4547. POH. 04/09/14 casing @ 3200'. POH w/ casing. 04/10 WOC. Tagged plug @ 3100'. Spotted 311. POH. WOC. 04/11/14 No Tag. F	C. 04/08/14 NO Tag. Re-Spott fet packer @ 4500'. Pressured u Tagged plug @ 4650'. POH w/ 0/14 RIH w/ tbg and spotted 30 35 sx @ 2100-1971. WOC. Tag Re-Spotted 35 sx @ 440. WOC.	ed 25 sx cement @ 6800-6547. WOC. Tagged plug up on csg. Pulled packer and spotted 25 sx tbg. Rigged up casing jacks. Pulled stretch. Cut osx cement @ 3250-3090. Pulled out of cement. gged plug @ 2000'. Spotted 35 sx cement @ 440-No Tag. Re-spotted 35 sx @ 440. WOC.		
cement@ 4800-4547. POH. 04/09/14 casing @ 3200'. POH w/ casing. 04/10 WOC. Tagged plug @ 3100'. Spotted 311. POH. WOC. 04/11/14 No Tag. F	C. 04/08/14 NO Tag. Re-Spott fet packer @ 4500'. Pressured u Tagged plug @ 4650'. POH w/ 0/14 RIH w/ tbg and spotted 30 35 sx @ 2100-1971. WOC. Tag Re-Spotted 35 sx @ 440. WOC.	ed 25 sx cement @ 6800-6547. WOC. Tagged plug up on csg. Pulled packer and spotted 25 sx tbg. Rigged up casing jacks. Pulled stretch. Cut osx cement @ 3250-3090. Pulled out of cement. gged plug @ 2000'. Spotted 35 sx cement @ 440-No Tag. Re-spotted 35 sx @ 440. WOC.		
cement@ 4800-4547. POH. 04/09/14 casing @ 3200'. POH w/ casing. 04/10 WOC. Tagged plug @ 3100'. Spotted 311. POH. WOC. 04/11/14 No Tag. F	C. 04/08/14 NO Tag. Re-Spott fet packer @ 4500'. Pressured u Tagged plug @ 4650'. POH w/ 0/14 RIH w/ tbg and spotted 30 35 sx @ 2100-1971. WOC. Tag Re-Spotted 35 sx @ 440. WOC.	ed 25 sx cement @ 6800-6547. WOC. Tagged plug up on csg. Pulled packer and spotted 25 sx tbg. Rigged up casing jacks. Pulled stretch. Cut osx cement @ 3250-3090. Pulled out of cement. gged plug @ 2000'. Spotted 35 sx cement @ 440-No Tag. Re-spotted 35 sx @ 440. WOC.		
cement@ 4800-4547. POH. 04/09/14 casing @ 3200'. POH w/ casing. 04/16 WOC. Tagged plug @ 3100'. Spotted 311. POH. WOC. 04/11/14 No Tag. F	C. 04/08/14 NO Tag. Re-Spott fet packer @ 4500'. Pressured to Tagged plug @ 4650'. POH w/0/14 RIH w/ tbg and spotted 30/35 sx @ 2100-1971. WOC. Tagger-Spotted 35 sx @ 440. WOC. Re-Spotted 35 sx @ 440. WOC. Rig Release Date:	ed 25 sx cement @ 6800-6547. WOC. Tagged plug up on csg. Pulled packer and spotted 25 sx tbg. Rigged up casing jacks. Pulled stretch. Cut osx cement @ 3250-3090. Pulled out of cement. gged plug @ 2000'. Spotted 35 sx cement @ 440-No Tag. Re-spotted 35 sx @ 440. WOC.		
cement@ 4800-4547. POH. 04/09/14 casing @ 3200'. POH w/ casing. 04/10 WOC. Tagged plug @ 3100'. Spotted 311. POH. WOC. 04/11/14 No Tag. F	C. 04/08/14 NO Tag. Re-Spott fet packer @ 4500'. Pressured to tragged plug @ 4650'. POH w/ 0/14 RIH w/ tbg and spotted 30 35 sx @ 2100-1971. WOC. Tag Re-Spotted 35 sx @ 440. WOC. Rig Release Date:	ed 25 sx cement @ 6800-6547. WOC. Tagged plug up on csg. Pulled packer and spotted 25 sx tbg. Rigged up casing jacks. Pulled stretch. Cut ex cement @ 3250-3090. Pulled out of cement. gged plug @ 2000'. Spotted 35 sx cement @ 440-No Tag. Re-spotted 35 sx @ 440. WOC.    DATE 5/1/4		
cement@ 4800-4547. POH. 04/09/14 casing @ 3200'. POH w/ casing. 04/10 WOC. Tagged plug @ 3100'. Spotted 311. POH. WOC. 04/11/14 No Tag. F  Spud Date:  Signature  Signature  Type or print name EDWAYS J. P. T. D. O.	C. 04/08/14 NO Tag. Re-Spott fet packer @ 4500'. Pressured to tragged plug @ 4650'. POH w/ 0/14 RIH w/ tbg and spotted 30 35 sx @ 2100-1971. WOC. Tag Re-Spotted 35 sx @ 440. WOC. Rig Release Date:	ed 25 sx cement @ 6800-6547. WOC. Tagged plug up on csg. Pulled packer and spotted 25 sx tbg. Rigged up casing jacks. Pulled stretch. Cut osx cement @ 3250-3090. Pulled out of cement. gged plug @ 2000'. Spotted 35 sx cement @ 440-No Tag. Re-spotted 35 sx @ 440. WOC.		
cement@ 4800-4547. POH. 04/09/14 casing @ 3200'. POH w/ casing. 04/16 WOC. Tagged plug @ 3100'. Spotted 311. POH. WOC. 04/11/14 No Tag. F  Spud Date:  Signature ————————————————————————————————————	C. 04/08/14 NO Tag. Re-Spott fet packer @ 4500'. Pressured to tragged plug @ 4650'. POH w/0/14 RIH w/ tbg and spotted 30 35 sx @ 2100-1971. WOC. Tag Re-Spotted 35 sx @ 440. WOC. Rig Release Date:  TITLE	ed 25 sx cement @ 6800-6547. WOC. Tagged plug up on csg. Pulled packer and spotted 25 sx tbg. Rigged up casing jacks. Pulled stretch. Cut osx cement @ 3250-3090. Pulled out of cement. gged plug @ 2000'. Spotted 35 sx cement @ 440-No Tag. Re-spotted 35 sx @ 440. WOC.    DATE 5/1/4   PHONE: 432-686-210		
cement@ 4800-4547. POH. 04/09/14 casing @ 3200'. POH w/ casing. 04/16 WOC. Tagged plug @ 3100'. Spotted 311. POH. WOC. 04/11/14 No Tag. F  Spud Date:  Signature ————————————————————————————————————	C. 04/08/14 NO Tag. Re-Spott fet packer @ 4500'. Pressured to tragged plug @ 4650'. POH w/0/14 RIH w/ tbg and spotted 30 35 sx @ 2100-1971. WOC. Tag Re-Spotted 35 sx @ 440. WOC. Rig Release Date:  TITLE	ed 25 sx cement @ 6800-6547. WOC. Tagged plug up on csg. Pulled packer and spotted 25 sx tbg. Rigged up casing jacks. Pulled stretch. Cut osx cement @ 3250-3090. Pulled out of cement. gged plug @ 2000'. Spotted 35 sx cement @ 440-No Tag. Re-spotted 35 sx @ 440. WOC.    DATE 5/1/4   PHONE: 432-686-210		
cement@ 4800-4547. POH. 04/09/14 casing @ 3200'. POH w/ casing. 04/16 WOC. Tagged plug @ 3100'. Spotted 311. POH. WOC. 04/11/14 No Tag. F  Spud Date:  Signature ————————————————————————————————————	C. 04/08/14 NO Tag. Re-Spott fet packer @ 4500'. Pressured to tragged plug @ 4650'. POH w/0/14 RIH w/ tbg and spotted 30 35 sx @ 2100-1971. WOC. Tag Re-Spotted 35 sx @ 440. WOC. Rig Release Date:  TITLE	ed 25 sx cement @ 6800-6547. WOC. Tagged plug up on csg. Pulled packer and spotted 25 sx tbg. Rigged up casing jacks. Pulled stretch. Cut ex cement @ 3250-3090. Pulled out of cement. gged plug @ 2000'. Spotted 35 sx cement @ 440-No Tag. Re-spotted 35 sx @ 440. WOC.    DATE 5/1/4		

Office Office	State of New M	lexico	Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Na	tural Resources	August 1, 2011
1625, N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283	92		WELL API NO. 30-025-28813
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
District III - (505) 334-6178	1220 South St. Fr	ancis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM S	37505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			026458
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPOS. DIFFERENT RESERVOIR. USE "APPLICA		LUG BACK TO A	7. Lease Name or Unit Agreement Name McClure F
PROPOSALS.)  1. Type of Well: Oil Well	Gas Well 🔲 Other		8. Well Number 1
2. Name of Operator			9. OGRID Number
Lynx Operating Co., Inc.			175701 10. Pool name or Wildcat
3. Address of Operator 600 N. Marienfeld, Ste. 918, Midla	nd, TX 79701		Denton Wolfcamp
4. Well Location			
	feet from the South	line and	feet from the <b>East</b> line
Section 14	<del></del>		NMPM County Lea
	11. Elevation (Show whether D		
	3778 GR		
12. Check A	ppropriate Box to Indicate	Nature of Notice	, Report or Other Data
NOTICE OF INT	ENTION TO:	5111	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WO	
TEMPORARILY ABANDON	CHANGE PLANS		RILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	<del>-</del>
DOWNHOLE COMMINGLE '			
OTHER:	П	OTHER:	П
	eted operations. (Clearly state al		nd give pertinent dates, including estimated date
of starting any proposed wor	k). SEE RULE 19.15.7.14 NMA		ompletions: Attach wellbore diagram of
proposed completion or reco	•		
	w/ tbg. ND BOP. Spotted 20 sx gging equipment and moved of		urface.
•	30 C		elded on "Above Ground Dry Hole
	: Loaded casing and tubing, C		
	· _out out ing and taking, c	at on deading on or	canea recations wro to on
Smud Data	Dia Balanca	Deter	
Spud Date:	Rig Release	Date:	
		<u>.                                    </u>	
I hereby certify that the information a	bove is true and complete to the	best of my knowled	ge and belief.
01000	,		
SIGNATURE CAN THE	TITLE Co	A()	DATE 5/1/14
Type or print name FowAZN +	PITT NGER E-mail addre	ss: ed@LVAH	CO - B17 PHONE: 432-686-7101
For State Use Only			
A DDD OVED DV			
APPROVED BY: Conditions of Approval (if any):	TITLE		DATE